

### INITIAL SITE ASSESSMENT

# ROUTE 74 FROM VIA CORDOVA TO ANTONIO PARKWAY, ORANGE COUNTY, CALIFORNIA CONTRACT NUMBER 43A0012 TASK ORDER NUMBER 12-086900-QW

Prepared for

CALIFORNIA
DEPARTMENT OF TRANSPORTATION
DISTRICT 12
ENVIRONMENTAL PLANNING DIVISION
IRVINE, CALIFORNIA

Prepared by

GEOCON ENVIRONMENTAL CONSULTANTS, INC.
6970 FLANDERS DRIVE
SAN DIEGO, CA 92121-2974
Tel. 858.558.6100
Fax. 858.558.8437

Email: environmental@geoconinc.com

**MAY 2000** 

### Memorandum

To: Smita Deshpande, Cheif Senior Environmental Planner

> Date: March 4, 2007 File No.: 12-ORA-74 KP: 1.7/4.8 (PM 1.0/30)

EA: 086900

From: Reza Aurausteh, Chief

ENVIRONMENTAL ENGINEERING BRANCH

Subject: Review of ISA Checklist (Initial Site Assessment Checklist) for SR-74 prepared by Department of Transportation, dated 4/17/03.

Dear Smita:

We have reviewed the above document and its findings are still valid.

If you have any questions please contact myself at (949) 724 2738 or Mr. David Yaghoubi of my staff at (949) 756 7828.

**Sincerely** 

Reza Aurasteh, Ph.D., P.E., Chief

Branch Chief, Environmental Engineering

C: Ahmed Abou- Abdou, Project Manager

Le-Ha Tran, Design Branch A

Alison Army: Environmental Planning

David Yaghoubi, Environmental Engineering



# Initial Site Assessment (ISA) Checklist

## **Project Information**

District 12, County ORA, Rout	e 74, Kilometer Post	(Post Mile) 1.0/2.9 E.	A 086900
Description: Proposed projec Avenue.	t widening of Route 7	74 from Calle Entrader	o to 0.48 km east of La Pata
Is the project on the HW Study	Minimal-Risk Projec	ts List (HW1)? No	
Project Manager: Marta Halab	i phone # 949(724-2	739)	
Project Engineer: Marta Halab	i phone # 949(724-2	2739)	
Project Screening			
Attach the project location magidentified.	to this checklist to	show location of all k	rnow and/or potential HW site
1. Project Features: New R/W	7? No Excavation	n? Yes Railroad Inv	volvement? No
Structure demolition/modifi	ication? No Sub	surface utility relocation	n? Maybe
2. Project Setting: City of San Avenue.	Juan Capistrano, Ro	ute 74 from Calle Entra	adero to 0.43 km east of La Pat
Rural or Urban Urba	<u>n</u>		
Current land usesRoute	e 74		
Adjacent land uses Resid	lential, agricultural		
(indu	strial, light industry,	commercial, agricultur	al, residential, etc.)
if any known hazardous wa	ste site is in or near t	he project area. If a k	ency records as necessary, to see nown site is identified, show its to provide pertinent information
4. Conduct Field Inspection. D	Date 4/17/03 Use the	attached map to locate	potential or known HW sites.
STORAGE STRUCTURES	/PIPELINES:		
Underground tanks	No	Surface tanks	
Sumps	No	Ponds	<u>No</u>
Drums	No	Basins	<del></del>
Transformers	No	_ Landfill	No
Other		ARI- 777	

# Initial Site Assessment (ISA) Checklist (continued)

<u>Contaminatio</u>	N: (spills, leaks, illega	l dumping, etc.)	
Surface staining	No	Oil sheen	No
Odors	No	Vegetation damage	No
Other			
Hazardous MA	ATERIALS: (asbestos, le	ead, etc.)	
Buildings		Spray-on fireproofing	
Pipe wrap		Friable tile	
Acoustical plast	er	Serpentine	
Paint		Other	
ISA Determinati	<del>-</del>		
waste involvement, is add	litional ISA work nee	te involvement? No, If there is ded before task orders can be additional time required:	prepared for the Investigation?
	9		
	prepared to transmi	t the ISA conclusions to the	Project Manager and Project
Engineer.  ISA Conducted b	y: Marta Hal	abi Date 4/17/03	<b>,</b>



### GEOTECHNICAL AND ENVIRONMENTAL CONSULTANTS



Task Order No. 12-086900-QW Project No. 08900-06-69 May 12, 2000

Ms. Marta Halabi California Department of Transportation District 12 Environmental Planning Division 3347 Michelson Drive, Suite 100 Irvine, California 92612

Subject:

INITIAL SITE ASSESSMENT

ROUTE 74 FROM VIA CORDOVA TO ANTONIO PARKWAY

ORANGE COUNTY, CALIFORNIA CONTRACT NUMBER 43A0012

TASK ORDER NUMBER 12-086900-QW

Dear Ms. Halabi:

In accordance with California Department of Transportation (Caltrans) Contract No. 43A0012 and Task Order No. 12-086900-QW, Geocon Environmental Consultants, Inc. (Geocon) has conducted an Initial Site Assessment (ISA) of the properties located along Route 74, between Via Cordova and Antonio Parkway, in Orange County, California.

The accompanying report presents the details of the ISA and summarizes the findings relative to the potential existing presence, as of the dates of the latest site visit/records review, of hazardous and potential hazardous materials/wastes within and next to the existing and proposed right-of-way. If there are any questions concerning the contents of the report, or if Geocon may be of further service, please contact the undersigned at your convenience.

JOEL C. KLOT

No. 4628

Joel C. Kloth, RG 4628 Sentor Project Geologist

Sincerely,

GEOCON ENVIRONMENTAL CONSULTANTS, INC.

Robert C. Owoc

Senior Staff Geologist

RCO:JCK:sc

(5) Addressee

6970 Flanders Drive ■ San Diego, California 92121-2974 ■ Telephone (619) 558-6100 ® Fax (619) 558-8437

### TABLE OF CONTENTS

I	NITIAL SITE ASSESSMENT	Page
I.	EXECUTIVE SUMMARY	i
1.	INTRODUCTION  1.1 Purpose  1.2 Scope of Services  1.3 Site Location	1 1
2.	GEOLOGIC AND GROUNDWATER CONDITIONS  2.1 Geologic Conditions	2 2 2
3.	FIELD SURVEY	2
4.	SITE HISTORY	3
<ul><li>5.</li><li>6.</li></ul>	GOVERNMENTAL AGENCIES - RECORDS REVIEW  5.1 Vista Information Solutions, Inc. Report of Database Search  5.1.1 Databases Searched  5.1.2 Identified Sites  5.1.3 Unmapped Sites  5.2 California Integrated Waste Management Board Review  5.3 Orange County Health Care Agency (OCHCA)  CONTACTS - PUBLIC AGENCIES  6.1 City of San Juan Capistrano Fire Department  6.2 Building Department Records  6.3 California Department of Conservation  6.4 USGS Topographic Map  6.5 Water Districts  6.6 Southern California Edison	
7.	CONCLUSIONS AND RECOMMENDATIONS	10
8.	LIMITATIONS	11
Fig 1. 2.	vures: Vicinity Map Topographic Map	
A. B. C.	pendixes: Task Order No. 12-086900-QW CRM Tech Report Vista Site Assessment Plus Reports References	

### I. EXECUTIVE SUMMARY

The objective of Task Order No. 12-086900-QW was to conduct an initial site assessment (ISA) of the properties 500 feet on either side of Route 74, from Via Cordova to Antonio Parkway, in Orange County, California. The searched area is herein referred to as the site. The purpose of the ISA was to evaluate the potential for existing environmental impacts to the site. Caltrans proposes to widen portions of Route 74 within the site.

A field survey was conducted, by way of public thoroughfares, focusing on properties designated for proposed right-of-ways. The properties adjacent to and in the vicinity of Route 74 were generally occupied by agricultural facilities and residential properties. The San Juan Creek bisects the site, and Route 74 passes over it.

Review of historic USGS topographic maps and historic aerial photographs indicated a road has been present along the site since 1902 extending from San Juan Capistrano to San Juan Hot Springs. The 1902 edition of the USGS topographic map indicated structures (presumably farmsteads) were present along the road through the project area. The 1949 USGS map indicated additional structures, including barns and unidentified orchards along the highway. The 1968 and 1975/1978 USGS maps indicated similar patterns of development. The 1980/1981 and 1988 USGS maps indicated the beginning of urbanization within the southwestern portion of the project area, and establishment of a small cluster of ponds on the San Juan Creek. Aerial photographs from 1937, 1958, 1967, 1983 and 1997 confirmed the depictions of the USGS maps from the same time periods. City of San Juan Capistrano records indicated the site is zoned alternatively as residential, large estate, small farms and vacant land reserved for future development.

A review of agency files and government databases, indicated potential on-site property usage, generation, or disposal of hazardous materials/wastes. On-site properties included in the ISA were listed underground storage tank (UST) operators, a listed leaking underground storage tank (LUST) site, small quantity generators (RCRA-SmGen) of non-acutely hazardous waste, and licensed solid waste facilities (SWLF), which are located as follows:

- Rancho Mission Viejo, located at 28672 Ortega Highway, and referenced in the LUST, CORTESE and UST databases was observed on the south side of Route 74 in the central portion of the site,
- Rancho Mission Viejo, located at 31471 Ortega Highway was referenced in the UST and RCRA-SmGen databases. The entrance to the facility was observed north of route 74 in the central portion of the site,
- Capistrano Wholesale Nursery, located at 29812 Ortega Highway is a listed UST site and was observed north of Route 74 in the eastern portion of the site,
- Talega Lift Station, located at 31500 Ortega Highway is a listed UST site and was observed north of Route 74 in the eastern portion of the site,

- Chiquita Reclamation Plant, located at 28793 Ortega Highway is a listed UST site. The entrance to the facility was observed north of Route 74 in the central portion of the site,
- Sierra Soils is a listed SWLF site, and was observed in the southeast portion of the site.

Based on the data presented in this assessment, there is a low to moderate likelihood that existing site conditions would impact Route 74 construction activities. The potential for the specific properties and general site conditions referenced below to affect the proposed construction activities depends on the location of proposed Route 74 widening and scope of construction activities.

- The Rancho Mission Viejo located at 28672 Ortega Highway Petroleum hydrocarbons were detected in groundwater monitoring wells at the Rancho Mission Viejo property. Groundwater was observed at depths ranging from approximately 13 to 17 feet below grade, flowing in a southeasterly direction (away from Route 74). Cases of impacted soil that have been granted closure by the Regional Water Resources Control Board or the Orange County Health Care Agency may be re-activated as a result of Caltrans proposed construction activities. The active Orange County Health Care Agency LUST case could affect excavation activities if groundwater is encountered.
- The potential for pesticide and herbicide impacts due to historic agricultural activities should be evaluated along the proposed route.
- The potential for lead impacts due to automobile exhaust should be evaluated along the shoulders of Route 74.
- Based on the location, distance from existing Route 74, and the nature of potential impacts, the UST, SWLF and RCRA-SmGen facilities identified during this investigation within the site boundary appear to have low potential for adverse impacts to the site.

### **INITIAL SITE ASSESSMENT**

### 1. INTRODUCTION

This report has been prepared in accordance with California Department of Transportation (Caltrans) Contract No. 43A0012 and Task Order No. 12-086900-QW. Geocon Environmental Consultants, Inc. (Geocon) has conducted an Initial Site Assessment (ISA) to evaluate the potential for hazardous materials/waste impacts on properties along Route 74 between Via Cordova and Antonio Parkway in Orange County, California. The area including 500 feet on each side of Route 74 is herein referred to as the site.

### 1.1 Purpose

The purpose of the ISA was to identify hazardous and potential hazardous materials/wastes within and next to the existing and proposed right-of-way. The guidelines used for the definition of hazardous materials/wastes are referenced in the *California Code of Regulations (CCR)*, "Title 22, Division 4.5".

### 1.2 Scope of Services

Geocon followed the scope of services outlined in Task Order No. 12-086900-QW, provided by Caltrans and dated February 2, 2000. The Task Order is included herein as Appendix A. The project scope included a review of various information sources for reported historical and current sources of hazardous materials/wastes, and a field survey of the properties located within the designated site area. Provisions for a survey of radon, asbestos-containing materials, wetlands, or methane gas were not included in the scope of services for the ISA.

### 1.3 Site Location

The site is located along Route 74 from Via Cordova to Antonio Parkway, in Orange County, California. The approximate location of the site is depicted on the Vicinity Map presented as Figure 1. A reproduction of portions of the USGS topographic map for the San Juan Capistrano and Cañada Gobernadora, California quadrangles, dated 1968 (photorevised 1981), and 1968 (photorevised 1988), respectively, is presented as Figure 2.

### 2. GEOLOGIC AND GROUNDWATER CONDITIONS

### 2.1 Geologic Conditions

Geologic information for properties located in the subject site search area was obtained from a map entitled *Geologic Map Of Orange County California*, *Showing Mines and Mineral Deposits*, compiled by P. K. Morton and R. V. Miller, and dated 1981. The map indicated the vicinity of the site as being underlain by Quaternary-aged alluvium, colluvium and terrace deposits, and Tertiary Capistrano Formation and Monterey Formation.

### 2.2 Regional Groundwater Quality and Occurrence

Information sources prepared by the State Water Resources Control Board (SWRCB) and the Regional Water Quality Control Board (RWQCB) were reviewed for information pertaining to groundwater quality and occurrence in the vicinity of the site. The information sources indicated that the site is located in the Ortega Hydrologic Subarea of the Mission Viejo Hydrologic Area (HA) within the San Juan Hydrologic Unit.

### 2.2.1 SWRCB San Diego Basin Plan

The SWRCB Plan indicated that groundwater of the San Juan Hydrologic Unit has been documented to exhibit Total Dissolved Solids (TDS) concentrations ranging from 250 to more than 2,000 milligrams per liter (mg/l). Groundwater of the San Juan Creek Unit is reportedly of poor quality and not suitable for domestic or irrigation purposes. Groundwater within the San Juan Hydraulic Unit is generally derived from wells drilled in alluvium, and is typically encountered at depths of less than 50 feet.

### 2.2.2 RWQCB San Diego Basin Plan

The RWQCB Plan indicated that groundwater occurring within the Ortega Hydrologic Subarea has existing beneficial uses for residential, municipal, agricultural, and industrial service supply purposes.

### 3. FIELD SURVEY

Representatives of Geocon conducted a field survey, by way of public thoroughfares, of the searched area on March 28, 2000. The purpose of the field survey was to observe existing conditions, focusing on properties designated for proposed right-of-ways, and to identify indicators of the potential

presence of hazardous materials/wastes. Observations noted during the field survey are summarized below.

The site appeared generally occupied by Route 74, residential properties, and agricultural facilities. The San Juan Creek bisected the east portion of the site. Utility poles, supporting overhead utility lines and electrical transformers were observed along the length of the site.

The portion of the site from Via Cordova to Shade Tree Lane was occupied by residential properties except for an unnamed produce store at 28341 Ortega Highway. The portion of the site from Shade Tree Lane to Antonio Parkway was occupied by a horse stable, orchards, nurseries and local water district facilities. A roadside directory indicated Rancho Mission Viejo Headquarters, DMB Ladera, and North Fork Cattle Ranch were located at 28811 Ortega Highway. The Chiquita Treatment Plant was listed at 28793 Ortega highway. Facilities associated with these addresses were not visible from public thoroughfares. Rancho Mission Viejo Field Office was located in the central portion of the site, south of Route 74 at 28672 Ortega Highway and included sheds and residences. Drums, labeled "non regulated waste" were stored near the shed. D&M Nursery was located at 29001 Ortega Highway, northwest of the intersection of Highway 74 and Antonio Parkway. The nursery supported greenhouses and unsheltered agricultural fields. A water district structure was also observed northwest of the referenced intersection. Recreational fields and storage buildings were located southwest of the referenced intersection. A sign indicated the property was operated by Sierra Soil Company and sold topsoil and compost.

### 4. SITE HISTORY

Geocon retained the services of CRM Tech to perform a review of relevant historic documents. CRM Tech reviewed historical maps, aerial photographs provided by Geocon, public records of the City of San Juan Capistrano and materials on file at local history collections. The findings of CRM Tech's investigation are summarized below:

- A road has been present along the site since 1902 extending from San Juan Capistrano to San Juan Hot Springs. The 1902 edition of the USGS topographic map indicated structures (presumably farmsteads) were present along the road through the project area. The 1949 USGS map indicated additional structures, including barns and unidentified orchards along the highway. The 1968 and 1975/1978 USGS maps indicated similar patterns of development. The 1980/1981 and 1988 USGS maps indicated the beginning of urbanization within the southwestern portion of the project area, and establishment of a small cluster of ponds on the San Juan Creek.
- Aerial photographs from 1937, 1958, 1967, 1983 and 1997 confirmed the depictions of the USGS maps from the same time periods.

• City of San Juan Capistrano records indicated the site is zoned alternatively as residential, large estate, small farms, and vacant land reserved for future development. Business licenses were issued by the city to three establishments, including a farm, a landscape company and a tack and feed store. The 1951 and 1952 Orange County directory listed a total of 28 addresses within their coverage area of the site. Of the 28 addresses, 25 were listed as residences and 3 were listed as ranches.

CRM Tech concluded that "Based on the observations discussed above, this study concludes that the developed potions of the project area have been used predominantly for agricultural and increasingly in recent years - residential purposes. A copy of the CRM Tech report, including qualifications of the preparer, is provided as Appendix B.

### 5. GOVERNMENTAL AGENCIES - RECORDS REVIEW

### 5.1 Vista Information Solutions, Inc. Report of Database Search

Caltrans provided Geocon with copies of two (2) reports prepared by Vista Information Solutions, Inc. (Vista) regarding governmental information database searches according to a prescribed search distance, which included the site. A search of databases was requested by Caltrans to obtain information regarding the potential existing presence of hazardous materials/wastes at the site at levels likely to warrant mitigation action pursuant to current regulatory guidelines. A reproduction of the reports prepared by Vista is presented in Appendix C.

The two reports prepared by Vista entitled Site Assessment Plus Report, for #08690K, dated February 2, 2000 and for SR 74, dated March 16, 2000, each included a Site Distribution Summary, a Site Inventory section, a Details section, a Description of Databases Searched section, maps of sites and a street map. The Site Distribution Summary section presented the databases reviewed, and the number of sites found in each database. The Site Inventory section identified the sites referenced in each database. The Details section presented site-specific information and source-specific data obtained from the databases and data regarding sites with incomplete information for mapping purposes. The Description of Databases Searched section presented databases reviewed and the current date of the databases.

Vista's SR 74 search was centered approximately at the intersection of Highway 74 and La Pata Avenue, at the eastern boundary of the site. Vista's #08690K search was centered approximately at the intersection of Highway 74 and Via Cordova, at the western boundary of the site.

### 5.1.1 Databases Searched

Vista performed searches of the following databases to a distance of 1-mile from two locations along Highway 74:

- National Priority List (NPL)
- Corrective Action Report (CORRACTS)
- State Priority List (SPL)
- State Equivalent to CERCLIS (SCL)
- Comprehensive Environmental Response, Compensation, and Liability Information System (CERCLIS)
- CERCLIS Formerly Under Review (CERC-NFRAP)
- Resource Conservation and Recovery Information System (RCRIS-TSD)
- Leaking Underground Storage Tank Information System (LUST)
- Permitted Solid Waste Landfills (SWLF)
- Sites with deed restrictions (DEED RSTR)
- State Index of Properties with Hazardous Waste (Cortese)
- Toxic Pit Cleanup Facilities (Toxic Pits)
- Federal and State Drinking Water Sources (Water Wells)
- RCRA Violations/Enforcement Actions (RCRA Viol)
- Toxic Release Inventory System (TRIS)
- Registered Underground or Aboveground Petroleum Storage Tanks (UST/AST)
- Emergency Response Notification System (ERNS)
- Registered Small or Large Generators of Hazardous Waste (GNRTR)
- State Spills List (SPILLS)

### 5.1.2 Identified Sites

Eighteen (18) sites were identified by Vista in one or more of the databases searched. The mapped locations of sites identified by Vista are presented within their respective reports in Appendix C. Geocon reviewed the Vista reports with respect to the site boundaries. Four (4) properties were mapped by Vista as being on the site. In addition, five (5) sites were mapped by Vista as in the vicinity of the site, and observed by Geocon as within the site boundary. The site locations were confirmed based on the field observations. The nine (9) properties identified by Vista or confirmed by Geocon to be on the site and to be of potential concern, are discussed below. Detailed information regarding the remaining identified properties is presented in Appendix C.

- 5 -

- Capistrano Wholesale Nursery, located at 29812 (identified as Map ID 1 of the referenced February 2, 2000, Vista Report), was referenced in UST as having a 550-gallon capacity unleaded gas tank with a status of "Other".
- Talega Lift Station, located at 31500 Ortega Highway (identified as Map ID 2 of the referenced February 2, 2000, Vista Report), was referenced in UST. Additional information regarding USTs on the property were not provided by Vista.
- Chiquita Water Reclamation Plant, located at 28793 Ortega Highway (identified as Map ID 3 of
  the referenced February 2, 2000, Vista Report and observed by Geocon north of Highway 74 in
  the central portion of the site), was referenced in UST as having six fiberglass USTs with a
  status of "Active/In Service", and ranging from 550 to 4,000-gallons capacity. Products stored
  were listed as unleaded gas, diesel and petroleum.
- Rancho Mission Viejo, located at 28672 Ortega Highway (identified as Map ID 3 of the March 16, 2000 referenced report, and observed by Geocon on the south side of Highway 74 in the central portion of the site), was referenced in LUST Cortese and UST. The UST listing indicated a 500-gallon capacity tank with a status of "Closed Removed". The Cortese listing indicated a leaking tank. The Regional Water Quality Control Board (RWQCB) and California Environmental Protection Agency (Cal-EPA) LUST databases indicated a gasoline release was reported on March 18, 1992, affecting soil only, a remediation plan was submitted on May 24, 1993, and affected soil was excavated and disposed, and a remediation plan submitted. The site was listed as referred to local agency and "open".
- Sierra Soils, located at 30921 La Pata Road (identified as Map ID 4 of the March 16, 2000, referenced report and observed by Geocon in the southeast portion of the site), was referenced in SWLF as an active, permitted, composting facility.
- San Juan Company, located at 31471 Ortega Highway (identified as Map ID 5 of the referenced February 2, 2000, Vista Report), was referenced in UST. Additional information regarding USTs on the property were not provided by Vista.
- Rancho Mission Viejo, located at 31471 Ortega Highway (also identified as Map ID 5 of the March 16, 2000, referenced report), was referenced in UST and RCRA-SmGen. The UST listing indicated a 500-gallon capacity petroleum tank with a status of "Active/In Service". RCRA-SmGen listing indicated non-acutely hazardous waste is generated on the property.
- Ford Motor Company, located at 33600 Ortega Highway (identified as Map ID 6 of the March 16, 2000, referenced report), was referenced in RCRA-SmGen, which indicated non-acutely hazardous waste is generated on the property. The Ford property was observed by Geocon to be located more than 1 mile east of the site.
- Casper Regional Park, located at 33401 Ortega Highway (also identified as Map ID 6 of the March 16, 2000, referenced report), was referenced in UST. The UST listing indicated a 500gallon capacity diesel tank and a 1,000-gallon unleaded gas tank, with a status of "Active/In

Service". The Casper Regional Park property was observed by Geocon to be located more than 1 mile east of the site.

### 5.1.3 Unmapped Sites

Six (6) properties were referenced in the orphan summary without reference to location. The unmapped sites are not designated on the map since the addresses and property identification, as provided to Vista, were incomplete. Based upon Geocon's observations, these unmapped sites are not likely to impact the site.

### 5.2 California Integrated Waste Management Board Review

A representative of Geocon reviewed information provided by the California Integrated Waste Management Board (CIWMB) regarding the La Pata Road Green Waste and Sierra Soil facilities. According to their permits, both properties are licensed composting facilities and subject to monthly inspection. Violations were not indicated in the reviewed records.

### 5.3 Orange County Health Care Agency (OCHCA)

A representative of Geocon reviewed information provided by the OCHCA regarding the Rancho Mission Viejo (RMV) LUST site. According to reports prepared by RMV's consultant, the former UST was located approximately 160 feet south of Ortega Highway. Groundwater was encountered at depths ranging from approximately 13 to 17 feet below grade and flowed in a southeasterly direction (away from Route 74).

According to the most recent analytical laboratory data (December 1999), groundwater was impacted by gasoline-range petroleum hydrocarbons including benzene, toluene, ethylbenzene, xylenes (BTEX) and methyl tertiary butyl ether (MtBE). Petroleum hydrocarbon impacts appeared to be limited to the vicinity of the former UST. Benzene concentrations ranged from below the laboratory's detection limit to 114 micrograms per liter (ug/l), toluene concentrations ranged from below the laboratory's detection limit to 10 ug/l, ethylbeneze concentrations ranged from below the laboratory's detection limit to 1.2 ug/l, xylene concentrations ranged from below the laboratory's detection limit to 4.0 ug/l and MtBE concentrations ranged from below the laboratory's detection limit to 230 ug/l.

Based upon the monitoring data, RMVs consultant requested case closure. In response to the request, OCHCA requested additional information including time versus concentration and time versus distance of lateral migration graphs, a hydrologic evaluation regarding the potential connection of the impacted groundwater aquifer to the San Juan Creek, a fire and explosion hazard survey of

potential receptors and a site map showing the remaining extent of impacted soil. As of the date of the file review, the requested information had not been provided.

### 6. CONTACTS - PUBLIC AGENCIES

Records for the site were not readily available, practically reviewable, or reasonably ascertainable at the following agencies:

- Office of Emergency Services
- Department of Water Resources
- County Recorder's Office
- County Court House
- Planning Department

### 6.1 City of San Juan Capistrano Fire Department

A representative of Geocon contacted a representative of the City of San Juan Capistrano Fire Department regarding UST permit records. The City of San Juan Capistrano Fire Department representative indicated that UST permit records were not available.

### 6.2 Building Department Records

Representatives of Geocon reviewed building department records at the City of San Juan Capistrano Building Departments to obtain information pertaining to the age of structures, present or past, on properties of potential concern on the subject site.

Records for Rancho Mission Viejo located at 28672 and 31471 Ortega Highway indicated various tenant improvements such as electrical permits and installation of a water softener. Other records were not available for commercial properties along Ortega Highway within the site boundary.

### 6.3 California Department of Conservation

The California Division of Oil and Gas (DOG) Field Map was reviewed by a representative of Geocon to obtain information concerning the site and properties in the vicinity of the site. The map depicted the location of oil and gas wells. The map indicated that the Union Oil Company of California O'Niell well is located approximately 8,000 feet northwest of the site, and the Exxon O'Niell Estates well is located approximately 8,000 feet southeast of the site. Both wells were referenced as "drilling-idle". The map did not indicate other oil wells closer to the subject site.

### 6.4 USGS Topographic Map

A review of the USGS topographic maps for portions of the San Juan Capistrano and Cañada Gobernadora, California quadrangles dated 1968 (photorevised 1981 and 1988 respectively), was performed to obtain information concerning the topography and previous development of the site and properties located in the vicinity of the site. On-site elevations depicted on the maps range from approximately 130 to 300 feet above Mean Sea Level (MSL). The San Juan Creek was depicted bisecting the eastern portion of the site. Surficial sand or gravel features were depicted in the northeast portion of the site. Dwellings or places of employment were depicted along Route 74. Orchards were depicted in the central portion of the site. Barns or warehouses were depicted on the south side of Route 74 in the central portion of the site. Color-coding indicated housing omission tint in the eastern portion of the site. Light-duty roads were also indicated on the site and site vicinity. Unimproved dirt roads were depicted in the eastern portion of the site. Route 74 was depicted as a medium-duty road.

### 6.5 Water Districts

A representative of Geocon contacted the City of San Juan Capistrano Water Department and the Santa Margarita Water District to obtain information regarding the reported source of water, method of sewage disposal, the location and depth of wells for the area, and reported local drinking waster problems. A representative of the San Juan Capistrano Water Department indicated that the city derives its water from the California Water Authority and there have not been drinking water contamination problems in the city. Information from the Santa Margarita Water District indicated that the district derives approximately 80% of its water from the California Water Authority and 20 % from local sources. Municipal drinking water wells are not located on the site, and sewage treatment would be provided by at the Chiquita Water Reclamation Plant.

### 6.6 Southern California Edison

Past documented discussions with Southern California Edison (SCE) representatives regarding SCE transformers indicated that it is unlikely that transformers contain PCBs at concentration levels requiring special management under the Environmental Protection Agency's rules. Federal law has prohibited the manufacture of transformers containing PCBs since 1977. In addition, SCE has never specified the purchase of distribution transformers utilized PCBs as the insulating/cooling fluid.

### 7. CONCLUSIONS AND RECOMMENDATIONS


Based on the data presented in this assessment, there is a low to moderate likelihood that existing site conditions at Rancho Mission Viejo, located at 28672 Ortega Highway (due to soil and groundwater impacts) would impact the site. The potential for the property to affect the proposed construction activities depends on the location of proposed Route 74 and the access pathways to Route 74. Review of OCHCA files indicate the former LUST was approximately 160 feet south of the existing Route 74 right-of-way. Based upon the anticipated scope of work (i.e., excavation of soil to less than 3 feet, backfill with road base and paving), depth to groundwater of greater than 13 feet, and groundwater flow direction to the southeast, it is not likely that the impacts from the LUST site would affect proposed Route 74 widening activities.

The potential for pesticide and herbicide impacts due to historic agricultural activities should be evaluated along the proposed construction route. The potential for lead impacts due to automobile exhaust should be evaluated along the shoulders of Route 74. Based on the location, distance from existing Route 74, and the nature of the potential impacts, the UST, SWLF and RCRA-SmGen facilities identified during this investigation within the site boundary appear to have low potential for adverse impacts to the site.

### 8. LIMITATIONS

This ISA report has been prepared solely for Caltrans, in consideration of Caltran's requirements. Other parties may rely on the findings and conclusions of the report for informational purposes only. However, Caltrans and other parties who may rely on the findings and conclusions of the report should recognize that this report is not a comprehensive site characterization and should not be construed as such. The findings and conclusions in this report are predicated on a field survey, a review of specified regulatory records, and a review of the historical usage of the property.

The information obtained is only relevant for the dates of the records reviewed or as of the date of the latest field survey. Thus, the information contained herein is only valid as of the date of the report, and will require an update to reflect recent records/field survey. Therefore, the report should only be deemed conclusive with the respect to the information obtained. No guarantee of the results of the study is implied within the intent of this report or any subsequent report, correspondence or consultation, either expressed or implied. The services performed were conducted in accordance with the local standard of care in the geographic region at the time the services were rendered. Caltrans and others should also understand that radon, lead-based paint, asbestos, lead in drinking water, wetlands, and methane gas were not addressed in the scope of services of this report.





CONSULTANTS, INC.

ENVIRONMENTAL SERVICES 6970 FLANDERS DRIVE - SAN DIEGO, CALIFORNIA 92121 - 2974 PHONE 858 558-6100 - FAX 858 558-8437

RCO / JMW

DSK / E0000


### VICINITY MAP

ROUTE 74 FROM ANTONIO PARKWAY TO VIA CORDOVA ORANGE COUNTY, CALIFORNIA

DATE 05-12-2000

PROJECT NO. 08900 - 06 - 69

FIG. 1





CONSULTANTS, INC.

ENVIRONMENTAL SERVICES 6970 FLANDERS DRIVE - SAN DIEGO, CALIFORNIA 92121 - 2974 PHONE 858 558-6100 - FAX 858 558-8437

RCO / JMW

DSK / E0000

### TOPOGRAPHIC MAP

ROUTE 74 FROM ANTONIO PARKWAY TO VIA CORDOVA ORANGE COUNTY, CALIFORNIA

DATE 05-12-2000

PROJECT NO. 08900 - 06 - 69

FIG. 2

1QUAD

ESTPLN/94

# APPENDIX



08900-06-69

# **CALTRANS DISTRICT 12**

3347 Michelson Dr. Suite 100 Irvine, CA 92612



# FAX TRANSMISSION

TO: NAME:	JOEL KLOTH	
IVAIVAE:	JOEL REVIE	DATE: 2/3/2000
	//BRANCH:	FAX NO.
GEOCON		858 ( 558-8437)
ROM:		
NAME:	MARTA HALABI	PHONE NO.
		949-724-2739
BRANCII:	CARLIDONIA CAL CALCIDIO DE LA	8-655-2739
BRANCH:	ENVIRONMENTAL ENGINEERING	FAX NO.
		949-756-7633
		<u> </u>
REFEREN	CE:	
UBJECT:	CONTRACT # 12-086900-QW	
7		
IESSAG	<b>E</b> ,	
ED3AG		
FASE CALL	MICHARD VEDIEV IE VOU DIVIDIO	
/	L ME BACK AND VERIFY IF YOU RECEIVED ALL CO	PIES OF OFFERED CONTRACT
_	_	
CEAN ONLY	USE AS ORIGINAL O ORIGINAL TO FOLLOW	PAGE: OF 6

STATE OF CALIFORNIA - BUSINESS, TRANSPORTATION AND HOUSING AGENCY

GRAY DAVIS, Governor

DEPARTMENT OF TRANSPORTATION DISTRICT 12 9347 MICHELSON DRIVE, SUITE 100 IRVINE, CA 92612



February 3, 2000

To:

Geocon, Environmental Consultants, Inc

Brian Stafford 6970 Flanders Drive San Diego, Ca 92121-2974

From:

DEPARTMENT OF TRANSPORTATION

District 12, Division Of Planning

Rc:

Task Order (T.O) No. 12-086900-QW, Contract # 43A0012, Initial Site Assessment (ISA) for Ortega Highway, Route 74 from 12 to Antonio Parkway, Widening Project.

The Department of Transportation, District 12, hereby offers your firm the subject Task Order contingent upon approval of funds by our Headquarters Office. The T.O. cost estimate indicates your firm to be the lowest bidder.

The purpose of T.O. is to perform the ISA. The ISA is undertaken to identify hazardous and potential contaminated and hazardous waste problems within four (4) proposed alternatives.

This T.O. is part of Caltran's new Contract # 43 A0012, and all provisions of that contract apply herein.

Please refer to the attached Site Plan for the location of the project, and four alternatives under the consideration.

The proposed project should clearly describe the specific information requirements important for the project, including assessors parcel numbers, site specific maps, and in depth land use history for particular parcel. The historic research is design to provide in depth historic research by a qualified historian. The historic research will be prepared by a qualified historian and should focus on the details of past land uses in the project area.

To proceed with T.O. the following documents must be received at our District 12, Office no later than February 7, 2000. Failure to submit these documents on/or before the said date will result in offering this T.O. to another contractor:

- A transmittal letter signed by the Contractor's Project Manager accepting the Task Order and its scope of work.
- 2. Signed ARD

0

3. List of subcontractors to be used in the T.O.

If you have any questions please call me at 949(724-2739)

Marta Halabi, Environmental Engineering

el. Halun

### Attachments:

- Attachment A; Location Map
- Attachment B; Copy of BCS
- Attachment C; Completion Schedule
- Attachment D; Task Order Acceptance/Refusal Document (ARD)

	Site Investigation Service	
Task Order Number: 12-086900-DW	3CS - Sout	BCS74.xls

			∓	A A County I see of the Branch	ě
150		4	4	Sear Cruet weeting	Ü
			₽	Technology Drawing	\$
			¥	Cervined industrial Hygienist	2
	, , , , , , , , , , , , , , , , , , ,		맕	Non-reg. Professional	×
-	18¥.		₹	Reg Geologist of Certifled Engineering Geologist	L
		ı		General Personnel	L
192.53	ĵ.		3 <sup>2</sup>	ISA Report-by-Percentage of hours in xem #1	u
2 400 00	: **	60	Ξ	Historic Research Report	
2 200 000		60	Į.	Record and Field Review	
Price	4	Quantity	Unit	ISA BID ITEMS	Ē
	Geocon 3			Enter Y if ISA report costs paid as a % of Item 1; "N' If costs are nourly as per Items 2, and 41-48. If no ISA work items, enter "N".	y
				INITIAL SITE ASSESSMENT	
	up) here -3			ORTEGA HWY ROUTE 74, WIDENING PROJECT	
		i			_
0.08975 078			· <b>·</b>	Project Name	
2,02/2000 1.1		12-08690	umber:		
	-S.	gion	atil Ne	San Contract	

Print this sheet and attach a copy to the Task Order Control Sheet

Total Cost \$

5,152.00

Initial Site Assessment

### APPENDIX C

### COMPLETION SCHEDULE

Task Order 12-086900-QW

Contract 43A0012

ITE	M ELEMENT DESCRIPTION	DELIVERY DATE	PENALTY
I.	Receive Task Order	February 3, 2000	
2.	Return Task Order	l'ebruary 7, 2000.	
3.	Prework Site Visit	February 14, 2000	
4,	Return Checklist		
5.	Return Schedule and Provide Safety	Plan	
6.	Prework Conference	March 12	
<i>7</i> .	Start Work	February 22, 2000	<del></del>
8.	Complete Sampling*		\$50/day
	(and repair/cleanup work site)	anil D	\ -
9.	Draft Report	March 13 2000 s	
10.	Caltrans Review	21, 2000	
11.	Final Report*	Nation 19, 2000	\$50/day
* De \$50.0	enotes key element of Completion Sch 00/day.	edule with liquidated dam	ages penalty of

We concur with this Completion Schedule on date

CONTRACT MANAGER (or designee)

Appendix D

43A0012 - Task Order Procedures

Task Order Acceptance Refusal Document (ARD)

### APPENDIX D

ULL FINDIN D
TASK ORDER ACCEPTANCE/REFUSAL DOCUMENT (ARD)
TO: CALTRANS DISTRICT # 12, Marta Halabi (Contract Manager) FROM: Gencon Euriton mental Consultants Inc (Contractor)
SUBJECT: Task Order # 12 - 086900-QW, as per SA43A0012
This task order offer was received on $\frac{2\sqrt{03/00}}{\sqrt{03/00}}$ (date)
Having reviewed the task order and attached completion schedule, this firm elects to:  (Initial one)  accept the task order. I further certify that consultation (Contractor) is in full compliance with Article XVIII - LIABILITY INSURANCE PROVISIONS, of the contract. If a current copy of the Certificate of Liability Insurance is not on file with the Contract Administrator, I understand that this task order may be terminated.
refuse the task order.
SIGNED
CONTRACTOR'S AUTHORIZED REPRESENTATIVE (Print Name)
I confirm that this task order has been accepted, refused by the contracting firm as indicated above.
SIGNED
M. Halali Felar. 3,2000
CONTRACT MANAGER (Date)
This document does not constitute a Notice-To-Proceed. This Task Order is not

This document does not constitute a Notice-To-Proceed. This Task Order is not valid until both a Notice-To-Proceed is executed and a Task Order Control Sheet is approved by the Contract Administrator and the Caltrans Accounting Service Center.

# APPENDIX



### HISTORICAL BACKGROUND RESEARCH REPORT

### A SEGMENT OF ORTEGA HIGHWAY (SR 74)

Between Via Cordova and Antonio Parkway/La Pata Avenue In and near the City of San Juan Capistrano Orange County, California

### Submitted to

Bob Owoc, Senior Staff Geologist Geocon Environmental Consultants, Inc. 6970 Flanders Drive San Diego, CA 92121-2974

### Submitted by

Bruce Love, Principal
Bai "Tom" Tang, Historian
CRM TECH
2411 Sunset Drive
Riverside, CA 92506

April 12, 2000

CRM TECH Contract #501

### 1 Introduction

Historical background research on the project area was conducted by Bai "Tom" Tang, CRM TECH historian (see App. 1 for qualifications), on the basis of historic maps, aerial photographs, public records of the City of San Juan Capistrano, and materials on file at the local history collections of the San Juan Capistrano and Santa Ana Public Libraries.

### 2 General Historical Background

The subject segment of Ortega Highway is located on the eastern edge of the City of San Juan Capistrano, a farming community for much of the 19th and 20th centuries. According to sources consulted for this study, a road was present along the project route at least by the 1890s (USGS 1902), but did not extend far beyond the nearby San Juan Hot Springs, a popular resort at the time (Hankey 1971:13). In 1923, the newly organized San Juan Capistrano Chamber of Commerce began a decade-long campaign to extend the road to Lake Elsinore (*ibid.*). By 1932, the road was completed and officially christened Ortega Highway in honor of Lt. José Francisco Ortega, a Spanish officer involved in the founding of Mission San Juan Capistrano in 1775-1776, and reputedly the first European to enter the area (*ibid.*:13-14; Hallan-Gibson 1990:16-17).

### 3 USGS Topographic Maps

USGS topographic maps dated between 1902 and 1981 were consulted for any evidence of previous development in the project area during the historic period. These maps are collected at the Science Library of the University of California, Riverside.

### 3.1 1902 USGS Map

The 1902 edition of USGS map, the earliest to depict the San Juan Capistrano area, shows approximately ten buildings, presumable farmsteads, along the road through the project area (Fig. 1). Most of these buildings were located in the southwestern half of the project area, within the present-day city boundary.

### 3.2 1949 USGS Maps

The 1949 edition of USGS maps show the continuing presence of buildings along Ortega Highway in the project area, which numbered approximately 20 by then, including several barns (Fig. 2). According to these maps, most of the project area within the present-day city boundary was covered by unidentified orchards at that time, especially along the southern side of the highway.

### 3.3 1968 and 1975/1978 USGS Maps

The 1968 and 1975/1978 editions of USGS maps indicate that the same development pattern observed in the project area during the 1940s persisted into the 1960s and 1970s, although a residential development had appeared just to the southwest by the 1970s




Figure 1. The project area in 1894-1899. (Source: USGS 1902)




Figure 2. The project area in 1946-1948. (Source: USGS 1949a; 1949b)

(USGS 1968a; 1969b; 1975; 1978). A gaging station had been established on the San Juan Creek prior to 1967-1968.

### 3.4 1980/1981 and 1988 USGS Maps

The 1980/1981 edition of USGS maps demonstrate the beginning of urbanization within the project area, as residential development began to expand into its southwestern portion (USGS 1980; 1981). On the northeastern corner of the project area, a small cluster of ponds came into being on the San Juan Creek between 1978 and 1985 (USGS 1988).

### 4 Aerial Photographs

Geocon Environmental Consultants, Inc., provided aerial photographs taken between 1937 and 1997 for this research.

### 4.1 1937 Aerial Photograph

An aerial photograph taken in 1937 reflects similar conditions in the project area as those indicated in the 1948 USGS maps. In addition to orchards in the southwestern half of the project area, the aerial photograph shows patches of cultivated farm land in and near the northeastern portion.

### 4.2 1958, 1967, and 1983 Aerial Photographs

Aerial photographs taken in 1958, 1967, and 1983 confirm the depiction of the project area in USGS maps from the same period.

### 4.3 1997 Aerial Photograph

An aerial photograph taken in 1997 shows that most of the southwestern portion of the project area, within the city boundary, had been developed into residential tracts.

### 5 City of San Juan Capistrano Records

Records of the City of San Juan Capistrano were consulted to identify possible commercial or industrial uses of land within the project area.

### 5.1 Zoning

City Planning Department records indicate that the project area within the city boundary is zoned alternatively as single-family residential, large estate, small farms, and growth management (vacant land reserved for future development). No commercial or industrial zones exist within the project area. The current zoning has been in effect since 1971.

### 5.2 Business Licenses

The Administrative Services and Business Licenses Division reports that the city has issued licenses to three business establishments on the 28000 block of Ortega Highway: Tanaka Farms at 28341 (since 1998), Pacific Scene Landscape, Inc., at 28461 (since 1989), and The Oak Tack and Feed at 28650 (since 1994).

### 6. Local Directories

Local directories published between 1901 and the 1950s were consulted in an effort to identify the nature and use of buildings shown in the project area by historic maps and aerial photographs. Due to the lack of listing by location or address, directories predating 1950 did not provide any useful information for this research. The 1951 edition of southern Orange County directory, however, lists a total of 28 addresses along Ortega Highway between Ganado Road (present-day Rancho Viejo Road) and the bridge over San Juan Creek, in most cases with no clear indication of their exact locations (Luskey's 1951:116). Among these 28 addresses, 25 are listed as residences, while the other 3 are listed as ranches (*ibid.*).

The same pattern is also noted in the 1952 directory (Luskey's 1952:87), with the occupations of the residents identified elsewhere in the volume. Starting from the intersection of Ganado Road, the 1952 directory contains the following listings along the same stretch of Ortega Highway:

North side	Lyle P. (Margaret) Mercado, rancher
North side	Harrison J. (Helen) Giddings, rancher
South side	Howard M. Lattimer, rancher; Kathleen Lattimer, librarian of the
	San Juan Capistrano Public Library
South side	Boyd L. (Ruth) Robertson, rancher
South side	Mrs. Blanch M. Robertson, rancher
North side	Howard (Anne) O'Brien, rancher
South side	Carl H. (Adele) Hankey, rancher
No. 28281	William W. Ottaway, South Coast News
North side	Vacant
South side	Frank Forster
South side	L. P. Mercado
South side	Fred (Josie) Llamas
South side	William H. (Maria) Browne, cabinet maker, San Clemente Cabinet
•	Shop
North side	Eldred T. (Jeannette) Lamb, rancher
South side	Adolph Oliveras, truck driver, City of San Clemente
South side	Cecil (Margaret) Martinez, rancher
South side	Joseph (Majorie) Tow, foreman, Rancho Mission Viejo
North side	Rancho Mission Viejo (lower), Arley H. (Alice) Leck, manager

### 7 Consultation with Local Historical Society

The San Juan Capistrano Historical Society was contacted for information pertaining to the history of the project area and the buildings noted above, but offered no comments.

### 8 Conclusion

Based on the research results discussed above, this study concludes that the developed portions of the project area have apparently been used predominantly for agricultural and—increasingly in recent years—residential purposes.

### REFERENCES

### Hallan-Gibson, Pamela

1990 Two Hundred Years in San Juan Capistrano: A Pictorial History. The Donning Company, Norfolk, Virginia.

### Hankey, Carl H.

1971 Personal Experiences in San Juan Capistrano. Oral historical interview conducted by Suzanne Jansen. In San Juan Capistrano Community History Project, Vol. 1. The Oral History Program, California State University, Fullerton, 1978.

### Luskeys

- 1951 Orange, Santa Ana, Tustin and Rural Street Address Directory. In Luskey's South Orange County City Directory. The Directory Services Company, Santa Ana.
- 1952 Orange County Beach Cities Criss Cross Street Address Directory. In Luskey's Orange County Beach Cities Criss Cross Directory. The Directory Services Company, Santa Ana.
- USGS (United States Geological Survey, U.S. Department of the Interior)
  - 1902 Map: Corona, Calif. (30', 1:125,000); surveyed in 1894 and 1899.
  - 1949a Map: San Juan Capistrano, Calif. (7.5', 1:24,000); aerial photographs taken in 1946, field-checked in 1948.
  - 1949b Map: Cañada Gobernadora, Calif. (7.5', 1:24,000); aerial photographs taken in 1946, field-checked in 1948.
  - 1968a Map: San Juan Capistrano, Calif. (7.5', 1:24,000); aerial photographs taken in 1967, field-checked in 1988.
  - 1968b Map: Cañada Gobernadora, Calif. (7.5', 1:24,000); aerial photographs taken in 1967, field-checked in 1988.
  - 1975 Map: Cañada Gobernadora, Calif. (7.5', 1:24,000); 1968 edition photorevised in 1975.
  - 1978 Map: San Juan Capistrano, Calif. (7.5', 1:24,000); 1968 edition photorevised in 1974.
- 1980 Map: Cañada Gobernadora, Calif. (7.5', 1:24,000); 1968 edition photorevised in 1978.
- 1981 Map: San Juan Capistrano, Calif. (7.5', 1:24,000); 1968 edition photorevised in 1977.
- 1988 Map: Cañada Gobernadora, Calif. (7.5', 1:24,000); 1968 edition photorevised in 1985.

#### APPENDIX 1: PERSONNEL QUALIFICATIONS

#### Bai "Tom" Tang, M.A., Project Historian

#### Education

1988-1993 1987 1982	Graduate Program in Public History/Historic Preservation, UC Riverside. M.A., American History, Yale University, New Haven, Connecticut. B.A., History, Northwestern University, Xi'an, China.
1994	"Assessing the Significance of Historic Archaeological Sites," presented by the Historic Preservation Program, University of Nevada, Reno.
2000	"Introduction to Section 106 Review," presented by the Advisory Council on Historic Preservation and the University of Nevada, Reno.

#### **Professional Experience**

1993-	Project Historian, CRM TECH, Riverside, California.
1993-1997	Project Historian, Greenwood and Associates, Pacific Palisades, California.
1991-1993	Project Historian, Archaeological Research Unit, UC Riverside.
1990	Intern Researcher, California State Office of Historic Preservation,
	Sacramento.
1990-1992	Teaching Assistant, History of Modern World, UC Riverside.
1988-1993	Research Assistant, American Social History, UC Riverside.
1985-1988	Research Assistant, Modern Chinese History, Yale University.
1985-1986	Teaching Assistant, Modern Chinese History, Yale University.
1982-1985	Lecturer, History, Xi'an Foreign Languages Institute, Xi'an, China.

#### Honors and Awards

1988-1990	University of California Graduate Fellowship, UC Riverside.
1985-1987	Yale University Fellowship, Yale University Graduate School.
1980, 1981	President's Honor List, Northwestern University, Xi'an, China.

#### **Cultural Resources Management Reports**

Preliminary Analyses and Recommendations Regarding California's Cultural Resources Inventory System (With Special Reference to Condition 14 of NPS 1990 Program Review Report). California State Office of Historic Preservation working paper, Sacramento, September 1990.

Approximately 300 cultural resources management reports with the Archaeological Research Unit, Greenwood and Associates, and CRM TECH, since October 1991.

#### Membership

California Preservation Foundation.

## APPENDIX

PROPERTY INFORMATION	CLIENT INFORMATION
Project Name/Ref #: SR 74	1200S0147
Corridor Study	Marta Halabi
San Juan Capistrano, CA 92675	District 12
Latitude/Longitude: ( 33.520874, 117.619085 )	Orange County, CA

Agency ∕ D		tribution Summary	within 1/8 mile	1/8 to 1/4 mile	1/4 to 1/2 mile	1/2 to 1 mile
A) Database	es searched t	o 1 mile:				
US EPA	NPL	National Priority List	0	0	0	0
US EPA	CORRACTS (TSD)	RCRA Corrective Actions and associated TSD	00	0	0	0
STATE	SPL	State equivalent priority list	0	0	0	0
B) Database	s searched to	1 mile:				
STATE	SCL	State equivalent CERCLIS list	0	0	0	0
US EPA	CERCLIS / NFRAP	Sites currently or formerly under review by US EPA	0	0	0	0
US EPA	TSD	RCRA permitted treatment, storage, disposal facilities	0	0	0	1
STATE REG	LUST	Leaking Underground Storage Tanks	0	0	0	4
STATE/ REG/CO	SWLF	Permitted as solid waste landfills, incinerators, or transfer stations	0	0	1	1
STATE	DEED RSTR	Sites with deed restrictions	0	0	0	0
STATE	CORTESE	State index of properties with hazardous waste	0	0	0	2
STATE	TOXIC PITS	Toxic Pits cleanup facilities	0	0	0	0
USGS/STATE	WATER WELLS	Federal and State Drinking Water Sources	0	0	0	0
	·-·		[			




For more information call VISTA information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 1200S0147 Date of Report: March 16, 2000

Version 2.6.1

	Site Dis	tribution Summary	within 1/8 mile	1/8 to 1/4 mile	1/4 to 1/2 mile	1/2 to 1 mile
	Satabaca Tur	oe of Records				
	ses searched t					
C) Databas	ses searched i	o i mile.				
US EPA	RCRA Viol	RCRA violations/enforcement actions	0	0	0	0
US EPA	TRIS	Toxic Release Inventory database	0	0	0	0
STATE	UST/AST	Registered underground or aboveground storage tanks	0	0	0	7
D) Databas	ses searched t	o 1 mile:	1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-			
US EPA	ERNS	Emergency Response Notification System of spills	0	0	0	0
US EPA:	GNRTR	RCRA registered small or large				
		generators of hazardous waste	0	0	0	3
STATE	SPILLS	State spills list	0	0	0	0
esearch in exceeds the limitation of customer processing the land of the land of the limitation of the land of the	a Phase I envese ASTM sear CHABILITY Creeds at its own rist insurer of the accurages officers, an	M standard E-1527 for standard federal a ironmental site assessment. A (-) indicate the characters.  k in choosing to rely on VISTA services, in whole or in pracy of the information, errors occurring in conversion ents, employees and independent contractors cannot resulting directly or indirectly from any information pr	es a distand eart, prior to pri of data, or for t be held liabl	roceeding wir customer's	arched be- th any transa- use of data. V	cause i ction. VIS ISTA and
esearch in exceeds the LIMITATION OF Customer proceannot be an affiliated compor expense sud	a Phase I envese ASTM sear CHABILITY Creeds at its own rist insurer of the accurages officers, an	ironmental site assessment. A (-) indicate rch parameters.  k in choosing to rely on VISTA services, in whole or in paracy of the information, errors occurring in conversion	es a distand eart, prior to pri of data, or for t be held liabl	roceeding wir customer's	arched be- th any transa- use of data. V	cause i ction. VII ISTA and
research in exceeds th LIMITATION OF Customer processing the commercial comme	a Phase I envese ASTM sear CHABILITY Creeds at its own rist insurer of the accurages officers, an	ironmental site assessment. A (-) indicate och parameters.  k in choosing to rely on VISTA services, in whole or in pracy of the information, errors occurring in conversion ents, employees and independent contractors canno	es a distand eart, prior to pri of data, or for t be held liabl	roceeding wir customer's	arched be- th any transa- use of data. V	cause i ction. VIS ISTA and:
esearch in exceeds th limitation of customer proceannot be an affiliated compor expense sud	a Phase I envese ASTM sear CHABILITY Creeds at its own rist insurer of the accurages officers, an	ironmental site assessment. A (-) indicate och parameters.  k in choosing to rely on VISTA services, in whole or in pracy of the information, errors occurring in conversion ents, employees and independent contractors canno	es a distand eart, prior to pri of data, or for t be held liabl	roceeding wir customer's	arched be- th any transa- use of data. V	cause i ction. VIS ISTA and
esearch in exceeds th limitation of customer proceannot be an affiliated compor expense sud	a Phase I envese ASTM sear CHABILITY Creeds at its own rist insurer of the accurages officers, an	ironmental site assessment. A (-) indicate och parameters.  k in choosing to rely on VISTA services, in whole or in pracy of the information, errors occurring in conversion ents, employees and independent contractors canno	es a distand eart, prior to pri of data, or for t be held liabl	roceeding wir customer's	arched be- th any transa- use of data. V	cause i ction. VIS ISTA and
esearch in exceeds th limitation of customer proceannot be an affiliated compor expense sud	a Phase I envese ASTM sear CHABILITY Creeds at its own rist insurer of the accurages officers, an	ironmental site assessment. A (-) indicate och parameters.  k in choosing to rely on VISTA services, in whole or in pracy of the information, errors occurring in conversion ents, employees and independent contractors canno	es a distand eart, prior to pri of data, or for t be held liabl	roceeding wir customer's	arched be- th any transa- use of data. V	cause i ction. VIS ISTA and
esearch in exceeds the sustained process of the sustained comport of the sustained comport expense sufficiency of the sustained comport expense sufficiency of the sustained comport expense sustained c	a Phase I envese ASTM sear CHABILITY Creeds at its own rist insurer of the accurages officers, an	ironmental site assessment. A (-) indicate och parameters.  k in choosing to rely on VISTA services, in whole or in pracy of the information, errors occurring in conversion ents, employees and independent contractors canno	es a distand eart, prior to pri of data, or for t be held liabl	roceeding wir customer's	arched be- th any transa- use of data. V	cause i ction. VII ISTA and
esearch in exceeds th limitation of customer proceannot be an affiliated compor expense sud	a Phase I envese ASTM sear CHABILITY Creeds at its own rist insurer of the accurages officers, an	ironmental site assessment. A (-) indicate ch parameters.  k in choosing to rely on VISTA services, in whole or in pracy of the information, errors occurring in conversion ents, employees and independent contractors canno	es a distand eart, prior to pri of data, or for t be held liabl	roceeding wir customer's	arched be- th any transa- use of data. V	cause i ction. VIS ISTA and
esearch in exceeds th limitation of customer proceannot be an affiliated compor expense sud	a Phase I envese ASTM sear CHABILITY Creeds at its own rist insurer of the accurages officers, an	ironmental site assessment. A (-) indicate ch parameters.  k in choosing to rely on VISTA services, in whole or in pracy of the information, errors occurring in conversion ents, employees and independent contractors canno	es a distand eart, prior to pri of data, or for t be held liabl	roceeding wir customer's	arched be- th any transa- use of data. V	cause i ction. VIS ISTA and
esearch in exceeds th limitation of customer proceannot be an affiliated compor expense sud	a Phase I envese ASTM sear CHABILITY Creeds at its own rist insurer of the accurages officers, an	ironmental site assessment. A (-) indicate ch parameters.  k in choosing to rely on VISTA services, in whole or in pracy of the information, errors occurring in conversion ents, employees and independent contractors canno	es a distand eart, prior to pri of data, or for t be held liabl	roceeding wir customer's	arched be- th any transa- use of data. V	cause i ction. VIS ISTA and
esearch in exceeds th limitation of customer proceannot be an affiliated compor expense sud	a Phase I envese ASTM sear CHABILITY Creeds at its own rist insurer of the accurages officers, an	ironmental site assessment. A (-) indicate ch parameters.  k in choosing to rely on VISTA services, in whole or in pracy of the information, errors occurring in conversion ents, employees and independent contractors canno	es a distand eart, prior to pri of data, or for t be held liabl	roceeding wir customer's	arched be- th any transa- use of data. V	cause i ction. VIS ISTA and:
esearch in exceeds th limitation of customer proceannot be an affiliated compor expense sud	a Phase I envese ASTM sear CHABILITY Creeds at its own rist insurer of the accurages officers, an	ironmental site assessment. A (-) indicate ch parameters.  k in choosing to rely on VISTA services, in whole or in pracy of the information, errors occurring in conversion ents, employees and independent contractors canno	es a distand eart, prior to pri of data, or for t be held liabl	roceeding wir customer's	arched be- th any transa- use of data. V	cause i ction. VIS ISTA and:






For More Information Call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403
Report ID: 1200S0147
Date of Re

Date of Report: March 16, 2000



### Street Map



#### SITE INVENTORY

	Α				В				С		D	
PROPERTY AND THE ADJACENT AREA MAP (within 1/8 mile)	S(TSD)		NFRAP				S	ا ا				
VISTA ID  DISTANCE D  DIRECTION >	CORRACT	SCI	CERCLIS/I	ınsı	SWLF DFFD RSTR	CORTESE	TOXIC PIT	RCRA VIO	IRIS	USI/ASI	ERNS	SPILLS
No Records	Four	nd						•				

	Α		В	agi, and	С		3
SITES IN THE SURROUNDING AREA  (Within: 1/8 - 1/4 mile)  VISTA I.  DISTANCE DIRECTION	티리이를	SCL CERCIIS/NERAP	SWLF DEED RSTR	TOXIC PITS WATER WELLS	<u>1</u>	UST/AST ERNS	SPILLS
No Rece	ords Foun	d					

			A						B				l		С			D.	
MAP ID	SITES IN THE SURROUNDING AREA (Within 1/4 - 1/2 mile)  VISTA ID DISTANCE DIRECTION	Z Z	CORRACTS(TSD)	SPL	108	CERCLIS/NFRAP	TSD	LUST	SWLF	DEED RSTR	CORTESE	TOXIC PITS	WATER WELLS	RCRA VIOL	TRIS	USI/ASI	ERNS	GNRTR	SPILLS
1	LA PATA ROAD GREENWASTE FACILITY 533824E 0.39 M 31748 LA PATA ROAD SAN JUAN CAPISTRANO, CA 92675	/							х										

1,113			Α						В						C			D	
MAP	SITES IN THE SURROUNDING AREA (within 1/2 - 1 mile)  VISTA I DISTANCE DIRECTIO	E	CORRACTS(ISD)	SPL	108	CERCLIS/NFRAP	ISD	LUST	SWLF	DEED RSTR	CORTESE	TOXIC PITS	WATER WELLS	RCRA VIOL	TRIS	UST/AST	ERNS	GNRTR	SPILLS
2	CALIFORNIA SILICA PRODUCTS CO 31302 ORTEGA SAN JUAN CAPISTRANO, CA 92675							X			х				i	X		х	



X = search criteria; r = tag-along (beyond search criteria).
For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 1200S0147 Version 2.6.1 Date of Report: March 16, 2000

			Α						В						С			D	
MAP ID	SITES IN THE SURROUNDING ARE (within 1/2 - 1 mile)	VISTA ID DISTANCE DIRECTION	CORRACTS(TSD)	TdS	108	CERCLIS/NFRAP	TSD	Inst	SWLF	DEED RSTR	CORTESE	TO XIC PITS	WATER WELLS	RCRA VIOL	TRIS	UST/AST	ERNS	GNRTR	STIIdS
2	OGLEBAY NORTON INDUSTRIAL SAND 31302 ORTEGA HWY SAN JUAN CAPISTRANO, CA 92675	5521324 0.63 MI E						х								Х			
3	RANCHO MISSION VIEJO 28672 ORTEGA SAN JUAN CAPISTRANO, CA 92675	1239230 0.74 MI W						х			Х					Х			
4	SIERRA SOILS 30921 LA PATA ROAD SAN JUAN CAPISTRANO, CA 92675	6831650 0.77 M/ S							X										
5	SAN JUAN COMPANY 31471 ORTEGA HWY 87 SAN JUAN CAPISTRANO, CA 92675	6947722 0.79 MI E														х			
5	RANCHO MISSION VIEJO 31471 ORTEGA SAN JUAN CAPISTRANO, CA 92675	1284456 0.79 M/ E														Х		X	
5	INDUSTRIAL ASPHALT 31511 ORTEGA HIGHWAY SAN JUAN CAPISTRANO, CA 92675	3200575 0.81 MJ E						х											
5	CALIFORNIA PORTLAND CEMENT CO 31511 ORTEGA HY SAN JUAN CAPISTRANO, CA 92675	12712810 0.81 MI E														х			
6	FORD MOTOR CO 33600 ORTEGA HWY TSD SITE SAN JUAN CAPISTRANO, CA 92675	5356626 0.99 MI W					Х											х	
6	CASPER REGIONAL PARK 33401 ORTEGA SAN JUAN CAPISTRANO, CA 92675	3497554 1.00 MI W														х			



			A					2.5	В						С			D	
UNMAPPED SITES	VISTA ID	NPL	CORRACTS(TSD)	SPL	108	CERCLIS/NFRAP	ISD	LUST	SWIF	DEED RSTR		TOXIC PITS		RCRA VIOL	TRIS	UST/AST	ERNS	GNRTR	SPILLS
ISAN JUAN CAPISTRANO LANDFILL	7448295														į				ĺ
NEAR SAN JUAN CREEK 300'N									X	- 1				1					İ
SAN JUAN CAPISTRANO, CA							_							_			$\dashv$		$\dashv$
LOMAS SAN JUAN MODEL HOME SITE	4223107											-	- 1						
TRACT 10139								X								1			
SAN JUAN CAPISTRANO, CA 92675									_	_		[	-		_				$\dashv$
PROVINCIAL PROPERTIES DUMP	7431245																	- 1	
UNKNOWN									X										. !
SAN JUAN CAPISTRANO, CA 92675												_							
SAN JUAN CAPISTRANO (DIST. 12)	6612759										ŀ		- 1			х		ŀ	
SAN JUAN CAPISTRANO, CA		L.					_					_					$\Box$		
PROVINCIAL PROPERTIES	6830417								х				ı						
SAN JUAN CAPISTRANO, CA											_							_	$\blacksquare$
RE ED RESERVOIR	4950373																	_	
LATITUDE 33-29-33N		ŀ																<b>x</b>	
SAN JUAN CAPISTRANO, CA 92675		<u> </u>			Ĺ					1							Ш		$\square$



#### **DETAILS**

#### PROPERTY AND THE ADJACENT AREA (within 1/8 mile)

No Records Found

#### SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile)

No Records Found

#### SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile)

VISTA VISTA ID#: LA PATA ROAD GREENWASTE FACILITY 5338246 Address\*: Distance/Direction: 0.39 MI / SW 31748 LA PATA ROAD Plotted as: Point SAN JUAN CAPISTRANO, CA 92675 STATE SWLF - Solid Waste Landfill / SRC# 6544 Agency ID: 30-AB-0364

MapiD

Agency Address:

LA PATA ROAD GREENWASTE FACILITY 31748 LA PATA ROAD

SAN JUAN CAPISTRANO, CA COMPOSTING FACILITY

Facility Type:

ACTIVE

**Facility Status:** Facility Life:

NOT REPORTED

Permit Status:

PERMITTED/LICENSED

Waste:

MIXED WASTE

#### SITES IN THE SURROUNDING AREA (within 1/2 - 1 mile)

VISTA. CALIFORNIA SILICA PRODUCTS CO VISTA ID#: 72961 Map ID Address\*: Distance/Direction: 0.63 MI/E. 31302 ORTEGA Plotted as: Point SAN JUAN CAPISTRANO, CA 92675 STATE UST - State Underground Storage Tank / SRC# 1612 EPA/Agency ID: N/A

2

**Agency Address:** 

CALIFORNIA SILICA PRODUCTS CO

31302 ORTEGA

S J CAPISTRANO, CA 92693

**Underground Tanks:** 

**Aboveground Tanks:** 

NOT REPORTED

Tanks Removed:

NOT REPORTED



\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403. Report ID: 120050147 Date of Report: March 16, 2000

Version 2.6.1

Tank   D:							
Tank Age:	Tank ID:	T000U	Tank :	Status:		ACTIVE/IN SE	RVICE
Tank Age:  Tank Size (Units):  Tank D:  Tank Contents:  Tank Age:  Tank Age:  Tank Age:  Tank Age:  Tank Bize (Units):  Tank Age:  Tank Age:  Tank Bize (Units):  Tank Bize (Units):  Tank Age:  Tank Age:  Tank Tank ID:  Tank Material:  Tank Material:  Tank Material:  Tank Material:  Tank Tank ID:  Tank Tan	1	DIESEL	Leak	Monito	ing:	Agency Cod	'e (*)
Tank ID:		NOT REPORTED	Jank I	Piping:	-	BARE STEEL	
Tank ID:	1 -	10000 (GALLONS)	Tank l	Materia	l:	BARE STEEL	
Tank Age: NOT REPORTED   Tank Piping: BARE STEEL   Tank Not Contents: UNKNOWN   Leak Monitoring: BARE STEEL   Tank Size (Units): 10000 (GALLONS)   Tank Material: BARE STEEL   Tank Not Contents: UNKNOWN   Leak Monitoring: Agency Code (*)   Tank Contents: UNKNOWN   Leak Monitoring: Agency Code (*)   Tank Size (Units): 10000 (GALLONS)   Tank Material: BARE STEEL   Tank Not Contents: UNKLEADED GAS   Tank Material: BARE STEEL   Tank Contents: UNKLEADED GAS   Tank Material: BARE STEEL   Tank Contents: UNKLEADED GAS   Tank Piping: BARE STEEL   Tank Material:		T000U	Tank :	Status:		ACTIVE/IN SE	RVICE
Tank Age: Tank Size (Units): Tank Contents: UMNNOWN Leak Monitoring: Agency Code (*) Tank Age: NOT REPORTED Tank Nice (Units): Tank Nice (Units): Tank Age: NOT REPORTED Tank Size (Units): Tank Nice (Units): Tank Age: NOT REPORTED Tank Age: Tank Piping: Tank Nice (Units): Tank Nice (Units): Tank Nice (Units): Tank Age: NOT REPORTED Tank Age: Tank Piping: Tank Age: Tank Piping: Tank Age: Tank Age: Tank Piping: Tank Age: Tank Age: Tank Age: Tank Piping: Tank Age: Tank Age: Tank Age: Tank Age: Tank Age: Tank Piping: Tank Age: Tank Age		DIESEL	Leak	Monitor	ing:	Agency Cod	e (*)
Tank ID: Tank ID: Tank DD: Tank Contents: UMKNOWN Tank Age: Tank Size (Units): Tank Age: Tank Piping: Tank Size (Units): Tank Age: Tank Piping: Tank Size (Units): Tank Age: Tank Piping: Tank Size (Units): Tank Material: Tank Piping: Tank Size (Units): Tank Age: Tank Piping: Tank Piping: Tank Size (Units): Tank Material: Tank Piping: Tank Piping: Tank Size (Units): Tank Age: Tank Piping: Tank Piping: Tank Size (Units): Tank Age: Tank Piping: Tank Piping: Tank Piping: Tank Size (Units): Tank Age: Tank Piping: Tank Piping: Tank Piping: Tank Size (Units): Tank Material: Tank Piping: Tank Piping: Tank Size (Units): Tank Material: Tank Piping: Tank	Tank Age:	NOT REPORTED	Tank l	Piping:		BARE STEEL	
Tank ID: Tank Contents:	_	10000 (GALLONS)	Tank I	Materia	<u>];                                    </u>	BARE STEEL	
Tank Age: NOT REPORTED TANK Piping: BARE STEEL Tank Size (Units): 10000 (CALLONS) TANK Material: BARE STEEL Tank ID: Tank Contents: UNLEADED GAS TANK Contents: UNLEADED GAS TANK Age: NOT REPORTED TANK Piping: BARE STEEL TANK Age: NOT REPORTED TANK Piping: BARE STEEL TANK Size (Units): 1000 (GALLONS) TANK Material: BARE STEEL TANK Size (Units): 1000 (GALLONS) TANK Material: BARE STEEL TANK Material: BARE STEEL  GORTESE / SRC# 4840 Agency Address:  List Name: CALIFORNIA SUICA PRODUCT 31302 ORTEGA SAM JUAN CAPSTRAMO, CA 928750000 LEAKING TANK Site ID: CAD040522351  Agency Address: SIZE ORTEGA MICHWAY SAM JUAN CAPSTRAMO, CA 928750000  CALIFORNIA SUICA PROD CO 31302 ORTEGA MICHWAY SAM JUAN CAPSTRAMO, CA 92875 Generator Class: Generator / SRC# 6597 EPA/Agency ID: N/A  Agency Address: CASICA PRODUCTS CO. 31302 ORTEGA HIGHWAY SAM JUAN CAPSTRAMO, CA 92875 Generates 100 4g./month of non-acutely hazardous STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID: N/A  Agency Address: 10/11/90 Leak Date: 10/11/90 Leak Report Date: 10/11/90 Leak Report Date: 10/11/90 Leak Cause: UNKNOWN Substance: DIESE Remediation Event: ENFORCEMENT: NONE TAKEN Remediation Status: CASE CLOSED  Media Affected: 50M ONLY Lead Agency: LOCAL AGENCY (COUNTY) Description / Comment: 10/CASEMUNI 9001240,543 NULLAN 901.20,6 WOEPTH: STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 PA/Agency ID: N/A  Agency Address: 1302 ORTEGA HIMM NAN CAPSTRAMO, CA 92675 STATE STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 PA/Agency ID: N/A  Agency Address: 1302 ORTEGA HIMM NAN CAPSTRAMO OR 92675 STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 PA/Agency ID: N/A  Agency Address: 1302 ORTEGA HIMM NAN CAPSTRAMO, CA 92675 STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 PEA/Agency ID: N/A  Agency Address: 1302 ORTEGA HIMM NAN CAPSTRAMO, CA 92675 STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 PEA/Agency ID: N/A  Agency Address: 1302 ORTEGA HIMM NAN CAPSTRAMO, CA 92675 STAT		T000U	Tank :	Status:		CLOSED REM	OVED
Tank Age: Tank ID: Tank ID: Tank Contents: UNLEADED GAS Leak Monitoring: Agency Code (*) Tank Age: Tank Piping: BARE STEEL  Agency ID: BARE STEEL  Agency ID: BUT2489  Agency Address:  Jago ORTESE / SRC# 4840  Agency Address: Jago ORTEGA SAM JUAN CAPSTRANO, CA 926750000  List Name: BUT2489  Agency Address: Jago ORTEGA HIGHWAY SAM JUAN CAPSTRANO, CA 926750000  Agency Address: Jago ORTEGA HIGHWAY SAM JUAN CAPSTRANO, CA 92675  Generator Class: Generator Class: Generator Class: Generator Class: Generator Ortega HIGHWAY SAM JUAN CAPSTRANO, CA 92675  Generator Ortega HIGHWAY SAM JUAN CAPSTRANO, CA 92675  Facility ID: Leak Date: Leak Date: Leak Cause: Leak Cau	Tank Contents:	UNKNOWN	Leak	Monitor	ing:	Agency Cod	e (*)
Tank ID: 1000U Tank Status: ACTIVE/IN SERVICE Tank Contents: UNLEAGED GAS Leak Monitoring: Agency Code (*) Tank Age: NOT REPORTED Tank Piping: BARE STEEL  Tank Size (Units): 1000 (GALLONS) Tank Material: BARE STEEL  CORTESE / SRC# 4840 Agency Address: 31302 ORTEGA SAN JUAN CAPISTRANO, CA 926750000 List Name: SUZ AM CAPISTRANO, CA 926750000 List Name: SUZ AM JUAN CAPISTRANO, CA 92675 Agency Address: 31302 ORTEGA HICHWAY SAN JUAN CAPISTRANO, CA 92675 Generator Class: Generator of Storage Tank / SRC# 6597 Generator Class: Generator of Storage Tank / SRC# 6597 Facility ID: CA SILCA PRODUCTS GO. 10/11/90 Leak Date: 10/11/90 Leak Report Date: 10/11/90 Leak Report Date: 10/11/90 Leak Report Date: 06520/91 Leak Cause: UNKNOWN Substance: 016561 Remediation Status: CASE CLOSED Media Affected: 500 Mit Storage Tank / SRC# 6597 Leak Cause: LOCAL AGENCY (COUNTY) Description / Comment: 10/CASENUM: 9001740, ASINHUM. 301.20. GWDEPTH: STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 LOCAL AGENCY (COUNTY) SAN JUAN CAPISTRANO, CA 92675 31302 ORTEGA HWY SAN JUAN CAPISTRANO, CA 92675	Tank Age:		Tank i	Piping:		BARE STEEL	
Tank Contents: UNLEADED GAS Leak Monitoring: Agency Code (*) Tank Age: NOT REPORTED Tank Piping: BARE STEEL  Tank Size (Units): 1000 (GALLONS)  Agency Address: ASAN JUAN CAPISTRANO, CA 926750000  List Name: SUZ489  List Name: SUZ489  List Name: SUZ489  List Name: SUZ489  RCRA-SmGen - RCRA-Small Generator / SRC# 6556  Agency Address: CALIFORNIA SULCA PRODUCT  31302 ORTEGA HIGHWAY  SAN JUAN CAPISTRANO, CA 926750000  LEAKING TANK  SITE LUST - State Leaking Underground Storage Tank / SRC# 6557  Facility ID: SUT132  Leak Date: 10/11/90  Leak Cause: UNKNOWN  Leak Cause: UNKNOWN  Substance: Remediation Event: ENFORCEMENT: NONE TAKEN  Remediation Event: CASE COSED  Media Affected: SOIL ONLY  Lead Agency: LOCAL AGENCY (COUNTY)  Description / Comment: LOCAL SPERANO, CA 92675  STATE LUST - State Leaking Underground Storage Tank / SRC# 6559  Leak Cause: UNKNOWN  Leak Cause: UNKNOWN  Leak Gapecy: LOCAL AGENCY (COUNTY)  Description / Comment: LOCAL AGENCY (COUNTY)  Description / Comment: LOCAL AGENCY (COUNTY)  Description / Comment: LOCAL AGENCY (COUNTY)  SAN JUAN CAPISTRANO, CA 92675  STATE LUST - State Leaking Underground Storage Tank / SRC# 65507  Leak Cause: UNKNOWN  Lead Agency: LOCAL AGENCY (COUNTY)  Description / Comment: LOCAL AGENCY (COUNTY)  Description / Comment: LOCAL AGENCY (COUNTY)  SAN JUAN CAPISTRANO, CA 92675  STATE LUST - State Leaking Underground Storage Tank / SRC# 65507  EPA/Agency ID: N/A  Agency Address: 31302 ORTEGA HWY  SAN JUAN CAPISTRANO, CA 92675  STATE LUST - State Leaking Underground Storage Tank / SRC# 65507  EPA/Agency ID: N/A  Agency Address: 31302 ORTEGA HWY  SAN JUAN CAPISTRANO, CA 92675  STATE LUST - State Leaking Underground Storage Tank / SRC# 65507  EPA/Agency ID: N/A  Agency Address: 31302 ORTEGA HWY  SAN JUAN CAPISTRANO, CA 92675  STATE LUST - State Leaking Underground Storage Tank / SRC# 65507  EPA/Agency ID: N/A	Tank Size (Units):	10000 (GALLONS)	Tank i	Materia	l:	BARE STEEL	
Tank Age: NOT REPORTED TANK Piping: BARE STEEL Tank Size (Units): 1000 (GALLONS)  Agency Address: Butter Agency Address: Butter Agency Address: Butter Agency Address: Agency	Tank ID:	7000U	Tank S	Status:		ACTIVE/IN SE	RVICE
Tank Size (Units): 1000 (GALLONS)  Tank Material: BARE STEEL  Agency Address: Agency Address: All Material: BARE STEEL  Agency Address: All Material: BARE STEEL  Agency Address: All Material: BARE STEEL  List Name: Size (List Name: Size Agency Address: All Material: BARE STEEL  List Name: Size (List Name: Size Agency Address: BIJOZ ORTEGA SAN JUAN CAPISTRANO, CA 926750000  List Name: Size (List Name: Size Agency Address: BIJOZ ORTEGA MICHWAY SAN JUAN CAPISTRANO, CA 92675  Agency Address: All Material: BARE STEEL  CALIFORNIA SILICA PROD CO  Agency Address: All Material: BARE STEEL  CALIFORNIA SILICA PROD CO  CAD040522351  CAD040522351  CAD040522351  CAD040522351  CAD040522351  CAD040522351  CAD040522351  CAD040522351  Agency Address: BIJOZ ORTEGA MICHWAY SAN JUAN CAPISTRANO, CA 92675  SAN JUAN CAPISTRANO, CA 92675  Facility ID: BIJOZ ORTEGA MIWY SAN JUAN CAPISTRANO, CA 92675  Facility ID: BIJOZ ORTEGA MIWY SAN JUAN CAPISTRANO, CA 92675  Facility ID: BIJOZ ORTEGA MIWY SAN JUAN CAPISTRANO CA 92675  SUBSTANCE: BIJOZ ORTEGA MIWY SAN JUAN CAPISTRANO CA 92675  Media Affected: BIJOZ ORTEGA MIWY SAN JUAN CAPISTRANO CA 92675  Media Affected: SOIL ONLY Lead Agency: LOCAL AGENCY (COUNTY) DESCRIPTION / Comment: CASE CLOSED  Media Affected: SIJOZ ORTEGA MIWY SAN JUAN CAPISTRANO, CA 92675  SIJOZ ORTEGA MIWY SIJOZ APRODUCTS SIJOZ ORTEGA MIWA SIJOZ APRODUCTS SIJOZ ORTEGA MIWY SIJOZ APRODUCTS SIJOZ ORTEGA MIWY SIJOZ APRODUCTS SIJOZ ORTEGA MIWA SIJOZ APRODUCTS SIJOZ ORTEGA MIWY SIJOZ APRODUCTS SIJOZ ORTEGA MIWY SIJOZ APRODUCTS SI	Tank Contents:	UNLEADED GAS	Leak	Monitor	ing:	Agency Cod	e (*)
TAILK MARCHIAL  CORTESE / SRC# 4840  Agency Address:  CALFORNIA SIZE (UNILS):  SAN JUAN CAPSTRANO, CA 926750000  List Name:  Site ID:  RCRA-SmGen - RCRA-Small Generator / SRC# 6556  Generator Class:  Generator Class:  Generator Class:  Generator State Leaking Underground Storage Tank / SRC# 6597  Facility ID:  Leak Date:  Leak Report Date:  Leak Report Date:  Leak Cause:  Leak Source:  JUKKNOWN  Substance:  Remediation Event:  Remediation Status:  CASE CLOSED  Media Affected:  Lead Agency:  Local Agency iD:  N/A  Agency Address:  JUKNOWN  Substance:  Remediation Status:  CASE CLOSED  Media Affected:  Leak Agency:  Local Agency (COUNTY)  Description / Comment:  CASE CLOSED TAILE STORAGE AREA  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597  Leak Cause:  Local Agency Country  Local Agency Country  Cause Cause:  Leak Cause:	Tank Age:	NOT REPORTED	Tank I	Piping:		BARE STEEL	
Agency Address:  CALIFORNIA SILICA PRODUCT 31302 ORTEGA SAN JUAN CAPISTRANO, CA 926750000  LEST Name:  SITE ID:  RCRA-SmGen - RCRA-Small Generator / SRC# 6556  RCRA-SmGen - RCRA-Small Generator / SRC# 6557  RCR-Small Generator / SRC# 6	_	1000 (GALLONS)	Tank i	Materia	l:	BARE STEEL	
List Name:  Site ID:  Site ID:  RCRA-Sm Gen - RCRA-Small Generator / SRC# 6556  Agency Address:  CALIFORNIA SILICA PROD CO 31302 ORTEGA HIGHWAY SAN JUAN CAPISTRANO, CA 92675  Generator Class:  Generator Class:  Generator State Leaking Underground Storage Tank / SRC# 6597  Facility ID:  Leak Date:  Leak Report Date:  CASSILIA PRODUCTS  Case Closed Date:  Leak Cause:  Leak Cause:  UNKNOWN  Leak Source:  Substance:  Remediation Event;  Remediation Status:  Media Affected:  Local Agency ID Surga Assimulm 301.20.GWDEPTH:  CASTATE LUST - State Leaking Underground Storage Tank / SRC# 6597  Leak Cause:  UNKNOWN  Leak Cause:  Leak Cause:  Leak Cause:  Local Agency ID Surga Assimulm 301.20.GWDEPTH:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597  Leak Cause:  Leak Cause:  Leak Cause:  Leak Cause:  Leak Cause:  Local Agency (Country)  Local Agency (Country)  Local Agency (Country)  Local Agency (Country)  Local Agency Surga Assimulm 301.20.GWDEPTH:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597  EPA/Agency ID:  N/A  CALIFORNIA SILICA PRODUCTS 31302 ORTEGA HWY SAN JUAN CAPISTRANO, CA 92675  SUL7489  SUL7489	CORTESE / SRC# 4840				Agenc	y ID:	9UT2489
RCRA-SmGen - RCRA-Small Generator / SRC# 6556  Agency Address:  Agency Address:  Generator Class:  Generator Class:  Generator Class:  Generator State Leaking Underground Storage Tank / SRC# 6597  Facility ID:  Leak Date:  Leak Report Date:  Case Closed Date:  Leak Cause:  Leak Cause:  Leak Cause:  Leak Source:  Substance:  Remediation Event:  Remediation Status:  Generator Class:  Generator State Leaking Underground Storage Tank / SRC# 6597  Facility ID:  Louid PRODUCTS CO.  31302 ORTEGA HWY  31302 ORTEGA HIGHWAY  31302 ORTEGA HWY  31302 ORTEGA HIGHWAY  31002 ORTEGA HWY  31002 ORTEG	List Name:		31302 ORTEGA SAN JUAN CAPISTRAN LEAKING TANK		6750000		
Agency Address:    CALIFORNIA SILICA PROD CO					EDA ID.		C 4 D040522251
Agency Address:    31302 ORTEGA HIGHWAY   SAN JUAN CAPISTRANO, CA 92675     Generator Class:   Generates 100 kg/month but less than 1000 kg/month of non-acutely hazardous waste     STATE LUST - State Leaking Underground Storage Tank / SRC# 6597   EPA/Agency ID:   N/A     Agency Address:   CASILICA PRODUCTS CO. 31302 ORTEGA HWY   SAN JUAN CAPISTRANO, CA 92675     Facility ID:   9017752     Leak Date:   10/11/90     Leak Report Date:   10/11/90     Case Closed Date:   UNKNOWN     Leak Cause:   UNKNOWN     Leak Source:   UNKNOWN     Substance:   UNKNOWN     Remediation Event:   ENFORCEMENT: NONE TAKEN     Remediation Status:   CASE CLOSED     Media Affected:   SOIL ONLY     Lead Agency:   LOCAL AGENCY (COUNTY)     Lead Agency:   LOCAL AGENCY (COUNTY)     Description / Comment:   CALIFORNIA SILICA PRODUCTS     STATE LUST - State Leaking Underground Storage Tank / SRC# 6597   EPA/Agency ID:   N/A     Agency Address:   31302 ORTEGA HWY   SAN JUAN CAPISTRANO, CA 92675     SUIZ-1489   SUIZ-1489     STATIST LUST - State Leaking Underground Storage Tank / SRC# 6597   EPA/Agency ID:   N/A     Agency Address:   SUIZ-1489   SUIZ-1489     STATIST - State Leaking Underground Storage Tank / SRC# 6597   EPA/Agency ID:   N/A     SAN JUAN CAPISTRANO, CA 92675   SUIZ-1489     SUIZ-1489   SUIZ-1489   SUIZ-1489     SUIZ-1489   SUIZ-1489   SUIZ-1489   SUIZ-1489     SUIZ-1489   SUIZ-1489   SUIZ-1489   SUIZ-1489   SUIZ-1489     SUIZ-1489   SUIZ-14	<del></del>	-Small Generator / Sk		POD CO	EPA ID:		[CAD040322331
STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID: N/A  Agency Address:  CA SILICA PRODUCTS CO. 31302 ORTEGA HWY SAN JUAN CAPISTRANO, CA 92675  Facility ID: Leak Date: 10/11/90  Leak Report Date: 10/11/90  Case Closed Date: 06/20/91  Leak Cause: UNKNOWN  Leak Source: UNKNOWN  Substance: Remediation Event: Remediation Status: CASE CLOSED  Media Affected: SOIL ONLY Lead Agency: Description / Comment: CASE STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID: N/A  Agency Address: 31302 ORTEGA HWY SAN JUAN CAPISTRANO, CA 92675  9012489  Facility ID: 9012408			31302 ORTEGA HIGHV SAN JUAN CAPISTRAN	NAY IO, CA 92		000 /- (	
Agency Address:  CA SILICA PRODUCTS CO. 31302 ORTEGA HWY SAN JUAN CAPISTRANO, CA 92675  Pacility ID:  Leak Date:  10/11/90  Leak Report Date:  06/20/91  Leak Cause:  UNKNOWN  Leak Source:  UNKNOWN  Substance:  Remediation Event:  Remediation Status:  CASE CLOSED  Media Affected:  SOIL ONLY  Lead Agency:  Description / Comment:  IOCASENUM: 90UT240,BASINNUM:901.20,GWDEPTH:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597   EPA/Agency ID:   N/A  Agency Address:  CASE CLOSED  N/A	Generator Class:				ess uran 10	oo kg.zinonui	or non-acutery nazardous
Facility ID: Leak Date: 10/11/90 Leak Report Date: 10/11/90 Leak Cause: Leak Source: UNKNOWN Leak Source: UNKNOWN Substance: Remediation Event; Remediation Status: CASE CLOSED Media Affected: Leak Agency: Leak Agency: Local Agency (County) Leak Agency: Description / Comment:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  Remediation ID:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agen	STATE LUST - State Lea	king Underground Sta	rage:Tank:/SRC#	6597	EPA/Ag	ency ID:	N/A
Leak Date:  Leak Report Date:  Case Closed Date:  Disservation Event:  Remediation Status:  Media Affected:  Leak Agency:  Description / Comment:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  Facility ID:  10/11/90  10/11			31302 ORTEGA HWY SAN JUAN CAPISTRAN		675		
Leak Report Date:  Case Closed Date:  UNKNOWN  Leak Source:  UNKNOWN  Substance:  Remediation Event:  Remediation Status:  CASE CLOSED  Media Affected:  Lead Agency:  Description / Comment:  TATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  Facility ID:  Description / CASE SOURCE	1 "						
Case Closed Date:  Leak Cause:  Leak Source:  UNKNOWN  Substance:  Remediation Event:  Remediation Status:  CASE CLOSED  Media Affected:  Lead Agency:  Description / Comment:  TATE LUST - State Leaking Underground Storage Tank / SRC# 6597  Facility ID:  LOCAL AGENCY (CASE CLOSE)  LOCAL AGENCY (COUNTY)  LOCASENUM: 9001240,BASINNUM:901.20,GWDEPTH:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597  EPA/Agency ID:  N/A							
Leak Cause:  Leak Source:  DIESEL  Remediation Event:  Remediation Status:  CASE CLOSED  Media Affected:  Local Agency (County)  Description / Comment:  DIESEL  LOCASENUM: 90017240,BASINNUM:901.20,GWDEP7H:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  Agency Address:  CASE CLOSED  LOCASENUM: 90017240,BASINNUM:901.20,GWDEP7H:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  N/A  CALIFORNIA SILICA PRODUCTS 31302 ORTEGA HWY SAN JUAN CAPISTRANO, CA 92675 90172489  DESCRIPTION OF THE PART OF		******					
Leak Source:    DIESEL							
Substance:  Remediation Event:  Remediation Status:  CASE CLOSED  Media Affected:  LOCAL AGENCY (COUNTY)  Lead Agency:  LOCASENUM: 90UT240,BASINNUM:901.20,GWDEPTH:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597  Agency Address:  CALIFORNIA SILICA PRODUCTS 31302 ORTEGA HWY SAN JUAN CAPISTRANO, CA 92675  9UT2489  PAGENTY:  PAGENTY:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597  EPA/Agency ID:  N/A  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597  EPA/Agency ID:  N/A  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597  EPA/Agency ID:  N/A							
Remediation Event:  Remediation Status:  CASE CLOSED  Media Affected:  Lead Agency:  Description / Comment:  COASENUM: 9001240,BASINNUM:901.20,GWDEPTH:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID: N/A  Agency Address:  CASE CLOSED  SOIL ONLY  LOCAL AGENCY (COUNTY)  LOCASENUM: 9001240,BASINNUM:901.20,GWDEPTH:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID: N/A  CALIFORNIA SILICA PRODUCTS 31302 ORTEGA HWY SAN JUAN CAPISTRANO, CA 92675  9012489							
Remediation Status:  CASE CLOSED  Media Affected:  LOCAL AGENCY (COUNTY)  Lead Agency:  LOCASENUM: 90UT240,BASINNUM:901.20,GWDEPTH:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597  Agency Address:  CALIFORNIA SILICA PRODUCTS 31302 ORTEGA HWY SAN JUAN CAPISTRANO, CA 92675  9UT2489				E TAKEN			
Media Affected:  Lead Agency:  Local Agency (County)  Description / Comment:  Locasenum: 90UT240, BASINNUM: 901.20, GWDEPTH:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID:  Agency Address:  CALIFORNIA SILICA PRODUCTS 31302 ORTEGA HWY SAN JUAN CAPISTRANO, CA 92675  9UT2489				TAREN			
Lead Agency:  Description / Comment:  IOCAL AGENCY (COUNTY)  LOCASENUM: 900T240,8ASINNUM:901.20,GWDEPTH:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597			·	<del></del> ,			
Description / Comment:  LOCASENUM: 90UT240,BASINNUM:901.20,GWDEPTH:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597				IINTY)			
Agency Address:  STATE LUST - State Leaking Underground Storage Tank / SRC# 6597 EPA/Agency ID: N/A  Agency Address:  SAN JUAN CAPISTRANO, CA 92675  90172489					IM:901.20.	GWDEPTH:	
Agency Address:  CALIFORNIA SILICA PRODUCTS 31302 ORTEGA HWY SAN JUAN CAPISTRANO, CA 92675 9UT2489  CALIFORNIA SILICA PRODUCTS 31302 ORTEGA HWY SAN JUAN CAPISTRANO, CA 92675							IN/Δ
Facility ID:  31302 ORTEGA HWY  SAN JUAN CAPISTRANO, CA 92675  9UT2489		ang underground sto			LFA/AU	ency ib.	147.63
racinty iu:			31302 ORTEGA HWY SAN JUAN CAPISTRAN		675		
Leak Date:							
	Leak Date:		03/13/33		<u>-</u>	- · · · · · · · · · · · · · · · · ·	



\* VISTA address includes enhanced city and ZIP.
For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 1200S0147

Version 2.6.1

Date of Report: March 16, 2000

Leak Report Date:	03/19/93					
Leak Detection Method:	OTHER MEANS					
Leak Cause:	UNKNOWN					
Leak Source:	UNKNOWN					
Substance:	GASOLINE					
Remediation Event:	LEAK STOPPED BY: CLOSE TANKLEAK STOP DATE: 04/02/93ENFORCEMENT: NONE TAKEN					
Remediation Status:	PRELIMINARY SITE ASSESSMENT WORKPLAN REQ					
Media Affected:	SOIL ONLY					
Lead Agency:	LOCAL AGENCY (COUNTY)					
Description / Comment:	BENEFICIAL: MUNICIPAL GROUNDWATER USELOCASENUM: 93UT15,BASINNUM:901.28,GWDEPTH:					
STATE LUST - State Leaking Underground	Storage Tank / SRC# 6658 EPA/Agency ID: N/A					
Agency Address:	CA SILICA PRODUCTS CO. 31302 ORTEGA HWY					
	SAN JUAN CAPISTRANO, CA 92675					
Facility ID:	9UT1752					
Leak Report Date:	10/11/19					
Site Assessment Plan Submitted:	11/01/19					
Case Closed Date:	06/20/19					
Substance:	DIESEL					
Remediation Status:	CASE CLOSED					
Media Affected:	SOIL ONLY					
Lead Agency:	LOCAL AGENCY					
Region / District:	SAN DIEGO REGION					
Description / Comment:	COUNTY: ORANGEXSTREET:REVIEW DATE: 05/28/19					
STATE LUST - State Leaking Underground	Storage Tank / SRC# 6658 EPA/Agency ID: N/A					
Agency Address:	CALIFORNIA SILICA PRODUCTS 31302 ORTEGA HWY SAN JUAN CAPISTRANO, CA 92675					
Facility ID:	9012489					
Leak Report Date:	03/19/19					
Site Assessment Plan Submitted:	03/19/19					
Substance:	GASOLINE					
Remediation Status:	PRELIMINARY SITE ASSESSMENT WORKPLAN REQ					
Media Affected:	SOIL ONLY					
Lead Agency:	LOCAL AGENCY					
Region / District:	SAN DIEGO REGION					
Description / Comment:	COUNTY: ORANGEXSTREET:REVIEW DATE: 08/31/19					
STATE LUST - State Leaking Underground	Storage Tank / SRC# 6667   EPA/Agency ID:   N/A					
Agency Address:	CALIFORNIA SILICA PRODUCTS CO 31302 ORTEGA HWY SAN JUAN CAPISTRANO, CA 92675					
Facility ID:	90UT240					
Case Closed Date:	06/20/91					
Substance:	DIESEL					
Remediation Status:	DETERMINE SITE STATUS/NOTIFY STATE BOARD					
Media Affected:	SOIL ONLY					
	LOCAL					
Lead Agency:						



\* VISTA address includes enhanced city and ZIP.
For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 1200S0147 Version 2.6.1

Date of Report: March 16, 2000

Page ≢10

Funding:	FEDERAL				
Description / Comment:	REFERRED: NOT REFERRED TO	REGIONAL			
TATE LUST - State Leaking Undergr	ound Storage Tank / SRC# 6667	EPA/Agency ID:	N/A		
Agency Address:	CALIFORNIA SILICA PRODUCT 31302 ORTEGA HWY SAN JUAN CAPISTRANO, CA 9 93UT15				
Facility ID:  Case Closed Date:	03/14/94				
Substance:	GASOLINE				
Remediation Event:	ACTION TAKEN BY RP				
Remediation Status:	DETERMINE SITE STATUS/NOTIF	Y STATE BOARD			
Media Affected:	SOIL ONLY				
Lead Agency:	LOCAL				
Funding:	FEDERAL				
Description / Comment:	REFERRED: NOT REFERRED TO	REGIONAL			

VISTA OGLEBAY NORTON INDUST	RIALSAND	VISTA ID#:	5521324	
Address*: 31302 ORIEGA HWY		Distance/Direction:	0.63 MI / E	
SAN JUAN CAPISTRANO; C	A 92675	Plotted as:	Point	
STATE LUST - State Leaking Underground Sto		EPA/Agency ID:	N/A	
Agency Address:	SAME AS ABOVE			
Facility ID:	9UT3523			
Leak Date:	06/28/97			
Leak Report Date:	07/31/97			
Leak Detection Method:	TANK TEST			
Substance:	DIESEL			
Remediation Status:	PRELIMINARY SITE ASSESSMENT	WORKPLAN REQ		
Media Affected:	SOIL ONLY			
Lead Agency:	LOCAL AGENCY (COUNTY)			
Description / Comment:	BENEFICIAL: MUNICIPAL GROUNDWATER USELOCASENUM: 97UT23,8ASINNUM:901.25,GWDEPTH:			
STATE LUST - State Leaking Underground Sto	rage Tank / SRC# 6658	EPA/Agency ID:	N/A	
Agency Address:	SAME AS ABOVE			
Facility ID:	9UT3523			
Leak Report Date:	07/31/19			
Site Assessment Plan Submitted:	07/31/19			
Substance:	DIESEL			
Remediation Status:	PRELIMINARY SITE ASSESSMENT	WORKPLAN REQ		
Media Affected:	SOIL ONLY			
Lead Agency:	LOCAL AGENCY			
Region / District:	SAN DIEGO REGION			
Description / Comment:	COUNTY: ORANGEXSTREET: LU	CAS CANYON ROADREVIE	W DATE: 08/29/19	



\* VISTA address includes enhanced city and ZIP.
For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 1200S0147 Version 2.6.1

Date of Report: March 16, 2000

Page #11

TATE UST - State Underground Sto	rage Tank / SRC# 6666	EPA/Agency ID:	N/A
Agency Address:	OGLEBAY NORTON INDUSTRIA 31302 ORTEGA HY SAN JUAN CAPISTRANO, CA	L SANDS	
Underground Tanks:	NOT REPORTED		
Aboveground Tanks:	NOT REPORTED		
Tanks Removed:	NOT REPORTED		
TATE LUST - State Leaking Underg	round Storage Tank / SRC# 6667	EPA/Agency ID:	N/A
Agency Address:	OGLEBOY NORTON INDUSTRIA 31302 ORTEGA HWY SAN JUAN CAPISTRANO, CA 9.		
Facility ID:	97UT24		
Substance:	DIESEL		
Remediation Status:	PRELIMINARY SITE ASSESSMENT		
Media Affected:	SOIL ONLY		
Lead Agency:	LOCAL		
Funding:	FEDERAL		
Description / Comment:	REFERRED: NOT REFERRED TO R	EGIONALSITE OPEN: YES	

VISTA RANCI	O MISSION VIEJO		VIST	A ID#:	1239230
Malignative of the 1997	ORTEGA		Dista	ance/Direction	: 0.74 MI / W
1.7 (1.10) (1.10) (1.10) (1.10) (1.10)	JAN CAPISTRANO.	CA 92675	Plott	ted as:	Point
STATE UST - State Und			EPA.	/Agency ID:	N/A
Agency Address:		RANCHO MISSION VIEJO 28672 ORTEGA SAN JUAN CAPISTRA, CA	92675		
Underground Tanks:	:	1			
Aboveground Tanks	s:	NOT REPORTED			
Tanks Removed:		NOT REPORTED			
Tank ID:	T001U	Tank Stat	us:	CLOSED REMO	OVED
Tank Contents:	UNKNOWN	Leak Mo	nitoring:	Agency Code	(7)
Tank Age:	NOT REPORTED	Tank Pipi	ng:	BARE STEEL	
Tank Size (Units):	500 (GALLONS)	Tank Mat	erial:	BARE STEEL	
CORTESE / SRC# 4840	)		Age	ncy ID:	9UT2195
Agency Address:		SAME AS ABOVE			
List Name:		LEAKING TANK			
Site ID:		9UT21 <b>9</b> 5			
STATE LUST - State Lea	king Underground SI	torage Tank / SRC# 65	97 EPA	/Agency ID:	N/A
Agency Address:		RANCHO MISSION VIEJO 28672 ORTEGA HWY SAN JUAN CAPISTRANO, C	CA 92675		
Facility ID:		9UT2195			
Leak Report Date:	4	03/18/92			
Contamination Con	firmed Date:	03/18/92			
Remediation Plan Da	ate:	05/24/93			
Leak Cause:		UNKNOWN			
Leak Source:		UNKNOWN			
Substance:		GASOLINE			
Remediation Event:		EXCAVATE AND DISPOSE			·



\* VISTA address includes enhanced city and ZIP.
For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403. Report ID: 1200S0147

Version 2.6.1

Date of Report: March 16, 2000 Page #12

a di ai Francis	ENFORCEMENT: NONE TAKEN				
Remediation Event:	REMEDIATION PLAN SUBMITTED				
Remediation Status:	SOIL ONLY				
Media Affected:	LOCAL AGENCY (COUNTY)				
Lead Agency:	BENEFICIAL: MUNICIPAL GROUNDWATER USELOCASENUM:				
Description / Comment:	92UT48,BASINNUM:901.28,GWDEPTH:				
STATE LUST - State Leaking Underground	d Storage Tank / SRC# 6658   EPA/Agency ID:   N/A				
Agency Address:	RANCHO MISSION VIEJO 28672 ORTEGA HWY				
	SAN JUAN CAPISTRANO, CA 92675				
Facility ID:	9UT2195				
Leak Report Date:	03/18/19				
Site Assessment Plan Submitted:	12/13/19				
Contamination Confirmed Date:	03/18/19				
Remediation Plan Date:	05/24/19				
Substance:	GASOLINE				
Remediation Event:	EXCAVATE AND DISPOSE				
Remediation Status:	REMEDIATION PLAN SUBMITTED				
Media Affected:	SOIL ONLY				
Lead Agency:	LOCAL AGENCY				
Region / District:	SAN DIEGO REGION				
Description / Comment:	COUNTY: ORANGEXSTREET:REVIEW DATE: 06/09/19				
STATE LUST - State Leaking Underground	i Storage Tank / SRC# 6667   EPA/Agency ID:   N/A				
Agency Address:	RANCHO MISSIÓN VIEJO 28675 ORTEGA HWY				
	SAN JUAN CAPISTRANO, CA 92675				
Facility ID:	92UT48				
Substance:	GASOLINE				
Remediation Event:	ACTION TAKEN BY RP				
Remediation Status:	REMEDIAL INVEST, FEASIBILITY STUDY, ETC.				
Media Affected:	GROUNDWATER				
Lead Agency:	LOCAL				
Funding:	FEDERAL				
Description / Comment:	REFERRED: NOT REFERRED TO REGIONALSITE OPEN: YES				
L	<del></del> · ·				

VISTA SIERRA SOILS	VISTA ID#:	6831650
Address*: 30921 LA PATA ROAD	Distance/Direction:	0. <i>TT</i> MI / S
SAN JUAN CAPISTRANO, CA 92675	Plotted as:	Point
STATE SWLF - Solid Waste Landfill / SRC# 6544	Agency ID:	30-AB-0372

SIERRA SOILS Agency Address:

30921 LA PATA ROAD

Facility Type:

SAN JUAN CAPISTRANO, CA COMPOSTING FACILITY

Facility Status:

NOT REPORTED

ACTIVE

Facility Life: Permit Status:

PERMITTED/LICENSED

Waste:

ANIMALS (WASTE BODIES)



\* VISTA address includes enhanced city and ZIP.
For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 1200S0147

Version 2.6.1

Date of Report: March 16, 2000

Page #13

VISTA SAN JUAN COM	PANY	VISTA ID#:	6947722	MapID
Address*: 31471 ORTEGA H		Distance/Direction	0.79 MI / E	
3177 01120111	STRANO, CA 92675	Plotted as:	Point	5
STATE UST - State Underground S		EPA/Agency ID:	N/A	
Agency Address:	SAN JUAN COMPANY 31471 ORTEGA HWY 87 SAN JUAN CAPISTRANO, CA			
Underground Tanks:	NOT REPORTED			
Aboveground Tanks:	NOT REPORTED			
Tanks Removed:	NOT REPORTED			j
VISTA RANCHO MISSIO	N-VIFIO	VISTA ID#:	1284456	Map ID
Address*: 31471 ORIEGA	•	Distance/Direction	0.79 M1 / E	
Consideration of the State of t	TRANO, CA 92675	Plotted as:	Point	5
STATE UST - State Underground S	torage Tank / SRC# 1612	EPA/Agency ID:	N/A	
- 11	RANCHO MISSION VIETO		-	Ì

TATE UST - State Unc	ierground Storage Tank	/ SKC# 1617	<u> </u>	PA/Agency ID:	N/A
Agency Address:		RANCHO MISSI 31471 ORTEGA			
Underground Tanks	:	1			
Aboveground Tank		NOT REPORTED			
Tanks Removed:		NOT REPORTED			
ank ID:	T001U	τ	ank Status:	ACTIVE/IN	SERVICE
ank Contents:	PETROLEUM	. L	eak Monitorii	ng: Agency Co	ode (^)
ank Age:	NOT REPORTED	T	ank Piping:	FIBERGLASS	;
lank Size (Units):	500 (GALLONS)	Ţ	ank Material:	BARE STEEL	
	A-Small Generator / SRC	C# 6556	Į	PA ID:	CAD983598731
Agency Address:		RANCHO MISSI 31471 ORIEGA			

	AN CAPISTRANO, CA 92675 ates 100 kg./month but less than 1000 kg./month of non-acutely hazard	dous
VISTA INDUSTRIAL ASPHALT Address*: 31511 ORTEGA HIGHWAY	VISTA ID#: 3200575.  Distance/Direction: 0.81 MI / E.	

Address*:	INDUSTRIAL ASPH 31511 ORTEGA H SAN JUAN CAPIS		VISTA ID#: Distance/Direction Plotted as:	3200575 2 0.81 MF/ E Point
		ground Storage Tank / SRC# 5873	EPA/Agency ID:	N/A
Agency Ad		INDUSTRIAL ASPHALT 31511 ORTEGA HIGHWAY SAN JUAN CAPISTRANO, CA		
Substance:		NOT HAZARD		
Remediatio	n Status:	CASE CLOSED/CLEANUP COM	MPLETE	
Responsible	Party:	INDUSTRIAL ASPHALT		



\* VISTA address includes enhanced city and ZIP.
For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 1200S0147 Version 2.6.1

Date of Report: March 16, 2000

Page #14

CALIFORNIA PORTL	AND CEMENT CO	VISTA ID#:	12712810	Ма							
				I							
	ANO, CA 92675	Plotted as:	Point								
ate Underground Store	age Tank / SRC# 6666	EPA/Agency ID:	N/A								
dress: d Tanks: nd Tanks:	CALIFORNIA PORTLAND 31511 ORTEGA HY SAN JUAN CAPISTRANO, NOT REPORTED NOT REPORTED										
ground Tanks: eground Tanks: Removed:  FORD MOTOR CO 33600 ORTEGA HWY SAN JUAN CAPISTRA SmGen - RCRA-Small General cy Address: rator Class: ISD / SRC# 6556 cy Address: te Waste Received: Disposal: erator: ge/Ireatment:  CASPER REGIONAL P 33401 ORTEGA SAN JUAN CAPISTRA	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,										
FORD MOTOR CO				Ma							
	/ TSD SITE			(							
		Plotted as:	Point	Ţ							
		EPA ID:	CAD981393085								
	SAME AS ABOVE										
	Generates 100 kg./mont waste	th but less than 1000 kg./mont	h of non-acutely hazardous								
RC# 6556		EPA ID:	CAD981393085								
	SAME AS ABOVE										
	NO	NO									
	NO		·								
<del>-</del>	NO										
atment:	NO										
C=A:CDED=DECIONEA1	D:A DV	VISTA ID#:	3497554	Ma							
CHOLEK KEGIONAT	E ATIVIN	B. B.	1" OO MI / Mi								
TO LOS OFFICA		Distance/Direction	1113 1.UU IVII.7 VV	I,:							
	ANO CA 02675	Plotted as:	Point	(							
SAN JUAN CAPISTR	ANO, CA 92675	Plotted as:	Point								
33401 ORTEGA SAN JUAN CAPISTRA UST - State Underground Stora ncy Address: erground Tanks:	ANO, CA 92675  age Tank / SRC# 1612  CASPER REGIONAL PARI 33401 ORTEGA SAN JUAN CAPISTRA, CA 2  NOT REPORTED	Plotted as:  EPA/Agency ID:									
SAN JUAN CAPISTR ate Underground Stora dress: d Tanks: nd Tanks:	age Tank / SRC# 1612 CASPER REGIONAL PARI 33401 ORTEGA SAN JUAN CAPISTRA, CA 2	Plotted as:  EPA/Agency ID:	Point								
SAN JUAN CAPISTR ate Underground Stora dress: d Tanks: nd Tanks: ved:	age Tank / SRC# 1612  CASPER REGIONAL PARI 33401 ORTEGA SAN JUAN CAPISTRA, CA 2  NOT REPORTED	Plotted as:  EPA/Agency ID:  1 92675	Point N/A								
SAN JUAN CAPISTR ate Underground Store dress: d Tanks: nd Tanks: ved:	age Tank / SRC# 1612  CASPER REGIONAL PARI 33401 ORIEGA SAN JUAN CAPISTRA, CA 2  NOT REPORTED  NOT REPORTED  Tank Sta	Plotted as:  EPA/Agency ID:  1 92675	Point N/A  ERVICE								
SAN JUAN CAPISTR ate Underground Store dress: d Tanks: nd Tanks: ved:	age Tank / SRC# 1612  CASPER REGIONAL PARI 33401 ORIEGA SAN JUAN CAPISTRA, CA 2  NOT REPORTED  NOT REPORTED  Tank Sta	Plotted as:  EPA/Agency ID:  4 92675  ACTIVE/IN S  Onitoring:  Agency Co	Point  N/A  ERVICE de (')								
SAN JUAN CAPISTR ate Underground Stora dress:  d Tanks: nd Tanks: ved:  TOOTU  nts:  UNLEADED GAS NOT REPORTED	age Tank / SRC# 1612  CASPER REGIONAL PARI 33401 ORTEGA SAN JUAN CAPISTRA, CA 2  NOT REPORTED  Tank Sta  Leak Mo	Plotted as:  EPA/Agency ID:  4 92675  ACTIVE/IN S  Initiating:  Agency Co  FIBERGLASS	Point  N/A  ERVICE de (')								
SAN JUAN CAPISTR ate Underground Stora dress:  d Tanks: nd Tanks: ved:  TOO1U  INS: NOT REPORTED	age Tank / SRC# 1612  CASPER REGIONAL PARI 33401 ORTEGA SAN JUAN CAPISTRA, CA 2  NOT REPORTED  Tank Sta Leak Mo	Plotted as:  EPA/Agency ID:  1 92675  ACTIVE/IN S  Indicating: Agency Co  FIBERGLASS  BARE STEEL	Point  N/A  ERVICE de (*)								
	31511 ORTEGA HY SAN JUAN CAPISTR ate Underground Stora dress: d Tanks: nd Tanks: nved: FORD MOTOR CO 33600 ORTEGA HW) SAN JUAN CAPISTR n - RCRA-Small Genera dress: class: srC# 6556 dress: ste Received: sal: atment:	31511 ORIEGA HY SAN JUAN CAPISTRANO, CA 92675 Late Underground Storage Tank / SRC# 6666  dress:  CALIFORNIA PORTLAND 31511 ORIEGA HY SAN JUAN CAPISTRANO, NOT REPORTED NOT REPORTED NOT REPORTED NOT REPORTED  NOT R	31511 ORTEGA HY SAN JUAN CAPISTRANO, CA 92675  Late Underground Storage Tank / SRC# 6666  CALIFORNIA PORTLAND CEMENT CO 31511 ORTEGA HY SAN JUAN CAPISTRANO, CA  d Tanks: NOT REPORTED NOT REPORTED  NOT REPORTED  NOT REPORTED  Plotted as:  VISTA ID#: Distance/Directio Plotted as:  VISTA ID#: Distance/Directio Plotted as: Plotted as:  SAN JUAN CAPISTRANO, CA 92675  IN - RCRA-Small Generator / SRC# 6556  Class:  Generates 100 kg./month but less than 1000 kg./month waste  EPA ID:  SAME AS ABOVE  SAME AS ABOVE  SIE Received: NO NO attment: NO  VISTA ID#: Distance/Directio Plotted as: Plotted a	31511 ORIEGA HY SAN JUAN CAPISTRANO, CA 92675  Tate Underground Storage Tank / SRC# 6666  TOTAL SAN JUAN CAPISTRANO, CA 92675  TOTAL SAN JUAN CAPISTRANO, CA 92							



Tank Age:

Tank Size (Units):

\* VISTA address includes enhanced city and ZIP.
For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Tank Piping:

Tank Material:

Report ID: 1200\$0147 Version 2.6.1

NOT REPORTED

500 (GALLONS)

Date of Report: March 16, 2000

**FIBERGLASS** 

BARE STEEL

#### **UNMAPPED SITES**

VISTA S	SAN JUAN CAPISTRANO L	ANDFILL	VISTA ID#:	7448295
4 1 1		same as above  Not reported  Not reported  No reported  N		14
	SAN JUAN CAPISTRANO, (		·	
VMUDS / SRC	# 5857		Agency ID:	9 300005NUR
Agency Add	ress:	SAME AS ABOVE		
•	nventory System ID:	NOT REPORTED		
Facility Type:	• -	Not reported		
System:	_			
Chapter 15 F	acility:	NO		
•	Assessment Test Facility:	NO		
Toxic Pits Cle	anup Act Facility:	NO		
RCRA Facility	<i>t</i> :	NO		
Department	of Defense Facility:	NO		
Open To Pub		NO		
•	laste Management Units:	1		
Rank:	_	NOT REPORTED		
Enforcement	s At Facility:	NO		
Violations At	*	NO		

VISTA LOMAS SAN JUAN M	ODEL HOME SITE	VISTA ID#:	4223107
[	NO, CA 92675		
IRACT 10139  SAN JUAN CAPISTRANO, CA 92675  ATE LUST - State Leaking Underground Storage Tank / SRC gency Address:  Accility ID:  Bak Date:  Bak Report Date:  Bak Report Date:  Bak Assessment Began:  Bollution Characterization Date:  Base Closed Date:  Bak Detection Method:  Bak Cause:  Bak Source:  Bak		EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Facility ID:	907197		
Leak Date:	04/12/85		
Leak Report Date:	04/23/85		
Site Assessment Began:	10/30/85		
Pollution Characterization Date:	07/14/86		
Remediation Plan Date:	09/29/86		
Case Closed Date:	12/11/91		
Leak Detection Method:	OTHER MEANS		
Leak Cause:	UNKNOWN		
Leak Source:	UNKNOWN		
Substance:	GASOLINE		
Remediation Event:	EXCAVATE AND TREAT		
Remediation Event:	LEAK STOPPED BY: OTHER MEA	NSENFORCEMENT: NONE	TAKEN
Remediation Status:	CASE CLOSED		
Media Affected:	AQUIFER (MUNICIPAL USE)		
Lead Agency:	LOCAL AGENCY (COUNTY)		
Description / Comment:	BENEFICIAL: MUNICIPAL GROU 85UT40,BASINNUM:901.27,GW		'M:



\* VISTA address includes enhanced city and ZIP.
For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 1200S0147 Version 2.6.1

Date of Report: March 16, 2000

#### UNMAPPED SITES CONT.

TATE LUST - State Leaking Undergroun	d Storage Tank / SRC# 6658	EPA/Agency ID:	N/A
Agency Address:	SAME AS ABOVE		
Facility ID:	907197		
Leak Report Date:	04/23/19		-
Site Assessment Plan Submitted:	04/23/19		
Site Assessment Began:	10/30/19		
Pollution Characterization Date:	07/14/19		
Remediation Plan Date:	09/29/19		
Case Closed Date:	12/11/19		
Substance:	GASOLINE		
Remediation Event:	EXCAVATE AND TREAT		
Remediation Status:	CASE CLOSED	· · · · · · · · · · · · · · · · · · ·	
Media Affected:	AQUIFER (MUNICIPAL USE)		
Lead Agency:	LOCAL AGENCY		
Region / District:	SAN DIEGO REGION		
Description / Comment:	COUNTY: ORANGEXSTREET: LA	NOVIA AVENUEREVIEW L	DATE: 08/27/19

VISTA PROVINCIAL PROPERTIES	DUMP	VISTA ID#:	7431245
Address*: UNKNOWN: SAN JUAN CAPISTRANO,			
VMUDS / SRC# 5857		Agency ID:	9 300002NUR
Agency Address:	SAME AS ABOVE		
Solid Waste Inventory System ID:	NOT REPORTED		
Facility Type:	Not reported		
Facility In State Board Waste Discharger	NO		
System:			
Chapter 15 Facility:	NO .		
Solid Waste Assessment Test Facility:	NO		
Toxic Pits Cleanup Act Facility:	NO		
RCRA Facility:	NO		
Department of Defense Facility:	NO		
Open To Public:	NO		
Number Of Waste Management Units:	1		
Rank:	NOT REPORTED		
Enforcements At Facility:	NO		
Violations At Facility:	NO		

VISTA PROVINCIAL PRO		VISTA ID#:	6830417
Address*: SAN JUAN CAPIS	STRANO, CA		
STATE SWLF - Solid Waste Landfill	/ SRC# 6544	Agency ID:	30-CR-0053
Agency Address:	SAME AS ABOVE		
Facility Type:	SOLID WASTE DISPO	OSAL FACILITY	
Facility Status:	OTHER		
Permit Status:	UNDER REVIEW		



\* VISTA address includes enhanced city and ZIP.
For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: **1200\$0147** *Version 2.6.1* 

Date of Report: March 16, 2000

#### **DESCRIPTION OF DATABASES SEARCHED**

#### A) DATABASES SEARCHED TO 1 MILE

NPL SRC#: 6558 VISTA conducts a database search to identify all sites within 1 mile of your property.

The agency release date for NPL was January, 2000.

The National Priorities List (NPL) is the EPA's database of uncontrolled or abandoned hazardous waste sites identified for priority remedial actions under the Superfund program. A site must meet or surpass a predetermined hazard ranking system score, be chosen as a state's top priority site, or meet three specific criteria set jointly by the US Dept of Health and Human Services and the US EPA in order to become an NPL site.

SPL SRC#: 6599 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Calsites Database: Annual Workplan Sites was October, 1999.

This database is provided by the Cal. Environmental Protection Agency, Dept. of Toxic Substances Control. The agency may be contacted at: 916-323-3400.

CORRACTS SRC#: 6556 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for HWDMS/RCRIS was December, 1999.

The EPA maintains this database of RCRA facilities which are undergoing "corrective action". A "corrective action order" is issued pursuant to RCRA Section 3008 (h) when there has been a release of hazardous waste or constituents into the environment from a RCRA facility. Corrective actions may be required beyond the facility's boundary and can be required regardless of when the release occurred, even if it predates RCRA.

#### B) DATABASES SEARCHED TO 1 MILE

CERCLIS SRC#: 6474 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for CERCLIS was October, 1999.

The CERCLIS List contains sites which are either proposed to or on the National Priorities List(NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL. The information on each site includes a history of all pre-remedial, remedial, removal and community relations activities or events at the site, financial funding information for the events, and unrestricted enforcement activities.



For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 1200S0147

Date of Report: March 16, 2000

Page #18

Cal Cerclis SRC#: 2462 VISTA conducts a database search to identify all sites within 1 mile of your property.

The agency release date for Ca Cerclis w/Regional Utility Description was June, 1995.

This database is provided by the U.S. Environmental Protection Agency, Region 9. The agency may be contacted at: . These are regional utility descriptions for California CERCLIS sites.

NFRAP SRC#: 6475 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for CERCLIS-NFRAP was October, 1999.

NFRAP sites may be sites where, following an initial investigation, no contamination was found, contamination was removed quickly, or the contamination was not serious enough to require Federal Superfund action or NPL consideration.

SCL SRC#: 6598 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Calsites Database: All Sites except Annual Workplan Sites (incl. ASPIS) was October, 1999.

This database is provided by the Department of Toxic Substances Control. The agency may be contacted at:

The CaiSites database includes both known and potential sites. Two-thirds of these sites have been classified, based on available information, as needing "No Further Action" (NFA) by the Department of Toxic Substances Control. The remaining sites are in various stages of review and remediation to determine if a problem exists at the site. Several hundred sites have been remediated and are considered certified. Some of these sites may be in long term-operation and maintenance.

RCRA-TSD SRC#: 6556 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for HWDMS/RCRIS was December, 1999.

The EPA's Resource Conservation and Recovery Act (RCRA) Program identifies and tracks hazardous waste from the point of generation to the point of disposal. The RCRA Facilities database is a compilation by the EPA of facilities which report generation, storage, transportation, treatment or disposal of hazardous waste. RCRA ISDs are facilities which treat, store and/or dispose of hazardous waste.

SWLF SRC#: 5945 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for City of Los Angeles Landfills was April, 1999.

This database is provided by the City of Los Angeles, Environmental Affais Department. The agency may be contacted at: 213-580-1070.



**SWLF** SRC#: 6544 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Ca Solid Waste Information System (SWIS) was November, 1999.

This database is provided by the Integrated Waste Management Board. The agency may be contacted at: 916-255-4021.

The California Solid Waste Information System (SWIS) database consists of both open as well as closed and inactive solid waste disposal facilities and transfer stations pursuant to the Solid Waste Management and Resource Recovery Act of 1972, Government Code Section 2.66790(b). Generally, the California Integrated Waste Management Board learns of locations of disposal facilities through permit applications and from local enforcement agencies.

Orange SRC#: 6433

VISTA conducts a database search to identify all sites within 1 mile of your property. County Landfill The agency release date for Orange County Landfills was April, 1999.

> This database is provided by the Orange County Health Care Agency. The agency may be contacted at: 714-834-3446.

WMUDS SRC#: 5857

VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Waste Management Unit Database System (WMUDS) was February, 1999.

This database is provided by the State Water Resources Control Board. The agency may be contacted at: 916-892-0323. This is used for program tracking and inventory of waste management units. This system contains information from: Facility, Waste Management Unit, SWAT Program and Report Summary Information, Chapter 15 (formerly Subchapter 15), TPCA and RCRA Program Information, Closure Information; also some information from the WDS (Waste Discharge System).

The WMUDS system also accesses information from the following databases from the Waste Discharger System (WDS): Inspections, Violations, and Enforcements. The sites contained in these databases are subject to the California Code of Regulations - Title 23. Waters.

LUST SRC#: 5873 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Region #9-SLIC List was August, 1996.

This database is provided by the Regional Water Quality Control Board, Region #9. The agency may be contacted at: 619-467-2980.


LUST RG6 SRC#: 6275 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Lahontan Region LUST List was August, 1999.

This database is provided by the Lahontan Region Six South Lake Tahoe. The agency may be contacted at: 530-542-5400.

LUST SRC#: 6277

VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Region #8-SLIC List was July, 1999.

This database is provided by the Regional Water Quality Control Board, Region #8. The agency may be contacted at: 909-782-4499.



LUST RG8 SRC#: 6542

VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Region #8-Santa Ana Regional Underground Tank Database List was October, 1999.

This database is provided by the Regional Water Quality Control Board, Region #8. The agency may be contacted at: 909-782-4499.

LUST RG9 SRC#: 6597 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Region #9 Leaking Underground Storage Tank List was October, 1999.

This database is provided by the Regional Water Quality Control Board, Region #9. The agency may be contacted at: 619-467-2980.

LUST SRC#: 6658

VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Lust Information System (LUSTIS) was January, 2000.

This database is provided by the California Environmental Protection Agency. The agency may be contacted at: 916-445-6532.

LUST SRC#: 6667

VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Orange County-Groundwater Cleanup Program was December, 1999.

This database is provided by the Orange County Health Care Agency. The agency may be contacted at: 714-834-3446.

CORTESE SRC#: 4840 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Cortese List-Hazardous Waste Substance Site List was April, 1998.

This database is provided by the Office of Environmental Protection, Office of Hazardous Materials. The agency may be contacted at: 916-445-6532.

The California Governor's Office of Planning and Research annually publishes a listing of potential and confirmed hazardous waste sites throughout the State of California under Government Code Section 65962.5. This database (CORTESE) is based on input from the following: (1)CALSITES-Department of Toxic Substances Control, Abandoned Sites Program Information Systems; (2)SARA Title III Section III Toxic Chemicals Release Inventory for 1987, 1988, 1989, and 1990; (3)FINDS; (4)HWIS-Department of Toxic Substances Control, Hazardous Waste Information System. Vista has not included one time generator facilities from Cortese in our database.; (5)SWRCB-State Water Resources Control Board; (6)SWIS-Integrated Waste Management Control Board (solid waste facilities); (7)AGT25-Air Resources Board, dischargers of greater than 25 tons of criteria pollutants to the air: (8)A1025-Air Resources Board, dischargers of greater than 10 and less than 25 tons of criteria pollutants to the air; (9)LTANK-SWRCB Leaking Underground Storage Tanks; (10)UTANK-SWRCB Underground tanks reported to the SWEEPS systems; (11) IUR-Inventory Update Rule (Chemical Manufacturers); (12) WB-LF- Waste Board -Leaking Facility, site has known migration; (13)WDSE-Waste Discharge System -Enforcement Action; (14)DTSCD-Department of Toxic Substance Control Docket.



For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403. Report ID: 1200S0147 Date of Report: March 16, 2000 Version 2.6.1

Deed Restrictions SRC#: 1703 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Deed Restriction Properties Report was April, 1994.

This database is provided by the Department of Health Services-Land Use and Air Assessment. The agency may be contacted at: 916-255-2014. These are voluntary deed restriction agreements with owners of property who propose building residences, schools, hospitals, or day care centers on property that is "on or within 2,000 feet of a significant disposal of hazardous waste".

California has a statutory and administrative procedure under which the California Department of Health Services (DHS) may designate real property as either a "Hazardous Waste Property" or a "Border Zone Property" pursuant to California Health Safety Code Sections 25220-25241. Hazardous Waste Property is land at which hazardous waste has been deposited, creating a significant existing or potential hazard to public health and safety. A Border Zone Property is one within 2,000 feet of a hazardous waste deposit. Property within either category is restricted in use, unless a written variance is obtained from DHS. A Hazardous Waste Property designation results in a prohibition of new uses, other than a modification or expansion of an industrial or manufacturing facility on land previously owned by the facility prior to January 1, 1981. A Border Zone Property designation results in prohibition of a variety of uses involving human habitation, hospitals, schools and day care center.

Toxic Pits SRC#: 2229 VISTA conducts a database search to identify all sites within 1 mile of your property.

The agency release date for Summary of Toxic Pits Cleanup Facilities was February, 1995.

This database is provided by the Water Quality Control Board, Division of Loans Grants. The agency may be contacted at: 916-227-4396.

Water Wells SRC#: 5384 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for USGS WATER WELLS was March, 1998.

The Ground Water Site Inventory (GWSI) database was provided by the United States Geological Survey (USGS). The database contains information for over 1,000,000 wells and other sources of groundwater which the USGS has studied, used, or otherwise had reason to document through the course of research. The agency may be contacted at 703-648-6819.

#### C) DATABASES SEARCHED TO 1 MILE

RCRA-Viols/Enf VISTA conducts a database search to identify all sites within 1 mile of your property.

The agency release date for HWDMS/RCRIS was December, 1999.

The EPA's Resource Conservation and Recovery Act (RCRA) Program identifies and tracks hazardous waste from the point of generation to the point of disposal. The RCRA Facilities database is a compilation by the EPA of facilities which report generation, storage, transportation, treatment or disposal of hazardous waste. RCRA Violators are facilities which have been cited for RCRA Violations at least once since 1980. RCRA Enforcements are enforcement actions taken against RCRA violators.



For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 1200S0147

Version 2.6.1

Page #22

UST's

SRC#: 1612

VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Underground Storage Tank Registrations Database was January, 1994.

This database is provided by the State Water Resources Control Board, Office of Underground Storage Tanks. The agency may be contacted at: 916-227-4364; Caution-Many states do not require registration of heating oil tanks, especially those used for residential purposes.

UST's SRC#: 5498 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Fullerton Underground Storage Tank List was December, 1998.

This database is provided by the Fullerton Fire Department. The agency may be contacted at: 714-738-3160; Caution-Many states do not require registration of heating oil tanks, especially those used for residential purposes.

UST's SRC#: 6589 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for City of Orange Underground Storage Tank List was September, 1999.

This database is provided by the City of Orange Fire Department. The agency may be contacted at: 714-288-2541; Caution-Many states do not require registration of heating oil tanks, especially those used for residential purposes.

UST's SRC#: 6590 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for City of Anaheim UST Listing was October, 1999.

This database is provided by the City of Anaheim. The agency may be contacted at: 714-765-4049; Caution-Many states do not require registration of heating oil tanks, especially those used for residential purposes.

UST's SRC#: 6666 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Orange County Underground Tank Facilities was December, 1999.

This database is provided by the Orange County Health Care Agency. The agency may be contacted at: 714-834-3446; Caution-Many states do not require registration of heating oil tanks, especially those used for residential purposes.

UST's SRC#: 6672 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Santa Ana City UST List was January, 2000.

This database is provided by the City of Santa Ana Fire Department. The agency may be contacted at: 714-647-5761; Caution-Many states do not require registration of heating oil tanks, especially those used for residential purposes.

AST's SRC#: 6669 VISTA conducts a database search to identify all sites within 1 mile of your property.

The agency release date for Aboveground Storage Tank Database was December, 1999.

This database is provided by the State Water Resources Control Board. The agency may be contacted at: 916-227-4364.



For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 1200S0147

Date of Report: March 16, 2000

Page #23

TRIS SRC#: 4946 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for TRIS was January, 1998.

Section 313 of the Emergency Planning and Community Right-to-Know Act (also known as SARA Title III) of 1986 requires the EPA to establish an inventory of Toxic Chemicals emissions from certain facilities (Toxic Release Inventory System). Facilities subject to this reporting are required to complete a Toxic Chemical Release Form (Form R) for specified chemicals.

#### D) DATABASES SEARCHED TO 1 MILE

ERNS SRC#: 6181 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for was August, 1999.

The Emergency Response Notification System (ERNS) is a national database containing records from October 1986 to the release date above and is used to collect information for reported releases of oil and hazardous substances. The database contains information from spill reports made to federal authorities including the EPA, the US Coast Guard, the National Response Center and the Department of Transportation. The ERNS hotline number is (202) 260-2342.

RCRA-LgGen SRC#: 6556 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for HWDMS/RCRIS was December, 1999.

The EPA's Resource Conservation and Recovery Act (RCRA) Program identifies and tracks hazardous waste from the point of generation to the point of disposal. The RCRA facilities database is a compilation by the EPA of facilities which report generation, storage, transportation, treatment or disposal of hazardous waste. RCRA Large Generators are facilities which generate at least 1000 kg./month of non-acutely hazardous waste (or 1 kg./month of acutely hazardous waste).

RCRA-SmGen SRC#: 6556 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for HWDMS/RCRIS was December, 1999.

The EPA's Resource Conservation and Recovery Act (RCRA) Program identifies and tracks hazardous waste from the point of generation to the point of disposal. The RCRA Facilities database is a compilation by the EPA of facilities which report generation, storage, transportation, treatment or disposal of hazardous waste. RCRA Small and Very Small generators are facilities which generate less than 1000 kg./month of non-acutely hazardous waste.

SPILL SRC#: 5849 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Orange County-Industrial Cleanups was January, 1999.

This database is provided by the Orange County Health Care Agency. The agency may be contacted at: 714-834-3446.

End of Report



For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 1200S0147

Page #24

Page #24

PROPERTY INFORMATION	CLIENT
Project Name/Ref #: 08690K	1200S0021
Orega Hwy Widening	Marta Halabi
San Juan Capistrano, CA 92675	District 12
Latitude/Longitude: (33.512636, 117.640166)	Irvine, CA

Agency / I	Site Dis	stribution Summary	within 1/8 mile	1/6 lo 1/4 mile	1/4 to 1/2 mile	1/2 to 1 mile
A) Databa	ses searched	o i mile:				Annual Control
US EPA		National Priority List	0	0	0	0
US EPA	(TSD)	RCRA Corrective Actions and associated ISD	0	0	0	0
STATE	SPL	State equivalent priority list	0	0	0	0
B) Databas	es searched t	i mile:				
STATE	SCL	State equivalent CERCLIS list	0	. 0	0	0
US EPA	CERCUS / NERAP	Sites currently or formerly under review by US EPA	. 0	0	0	0
US EPA	TSD	RCRA permitted treatment, storage, disposal facilities	0	1	0	0
STATE REG	LUST	Leaking Underground Storage Tanks	0	0	1	0
STATE/ REG/CO	SWLF	Permitted as solid waste landfills, incinerators, or transfer stations	0	0	0	5
STATE	DEED RSTR	Sites with deed restrictions	0	0	0	0
STATE	CORTESE	State index of properties with hazardous waste	0	0	1	0
STATE	TOXIC PITS	Toxic Pits cleanup facilities	0	0	0	0
JSGS/STATE	WATER WELLS	Federal and State Drinking Water Sources	0	0	0	0
		q				



For more information call VISTA information Solutions, Inc. at 1 - 800 - 767 - 0403.


Report ID: 1200S0021

Date of Report: February 2, 2000

Page #1


	RCRA Viol RCRA violations/enforcements TRIS Toxic Release Inventory databate UST/AST Registered underground or aboveground storage tanks  asses searched to 1 mile:  ERNS Emergency Response Notification System of spills GNRTR RCRA registered small of large generators of hazardous waste SPILLS State spills list  timeets the ASTM standard E-1527 for standard for a Phase Lenvironmental site assessment: A (-) those ASTM search parameters.  If LIABILITY Creeds at its own tisk in choosing to rely on VISTA services, in what insurer of the accuracy of the information, errors occurring in capanets, officers, agents, employees and independent contract	stribution Summary	within 1/8	1/8 to 1/4 mile	1/4 to 1/2 mile	1/2 to 1 mile
Agency /	Database - Ty	pe of Records				
C) Databa	A RCRA Viol RCRA violations/enforcement of TRIS Toxic Release inventory data usit/AST Registered underground or aboveground storage tanks aboveground storage and storage aboveground storage aboveground storage aboveground storage and storage aboveground storage aboveground storage are proceeds at its own tisk in choosing to rely on VISTA services, in the proceeds at its own tisk in choosing to rely on VISTA services, in the proceeds at its own tisk in choosing to rely on VISTA services, in the proceeds at its own tisk in choosing to rely on VISTA services, in the proceeds at its own tisk in choosing to rely on VISTA services, in the proceeds at its own tisk in choosing to rely on VISTA services, in the proceeds at its own tisk in choosing to rely on VISTA services, in the proceeds at its own tisk in choosing to rely on VISTA services, in the proceeds at its own tisk in choosing to rely on VISTA services, in the proceeds at its own tisk in choosing to rely on VISTA services, in the proceeds at its own tisk in choosing to rely on VISTA services, in the proceeds at its own tisk in choosing to rely on VISTA services, in the proceeds at its own tisk in choosing to rely on VISTA services, in the proceeds at its own tisk in choosing to rely on VISTA services, in the proceeds at its own tisk in choosing to rely on VISTA services, in the proceeds at its own tisk in choosing to rely on VISTA services, in the proceeds at its own tisk in choosing to rely on VISTA services, in the proceeds at its own tisk in choosing to rely on VISTA services, in the proceeds at its own tisk in choosing to rely on VISTA services.					
US EPA	A RCRA Viol RCRA violetions/enforcement A TRIS Toxic Release (rivertory da UST/AST Registered underground of aboveground storage tank tabases searched to 1 mile:  A ERNS Emergency Response Notifications of spills  A ERNS Emergency Response Notifications of spills  A GNRTR RCRA registered small on la generators of hazardous with spills list.  Profit meets the ASTM standard E 1527 for standard in a Phase Lenvironmental site assessment. And these ASTM search parameters.  ON OF UABILITY en proceeds at its own risk in choosing to rely on VISTA services, be an insurer of the accuracy of the information, errors occurring a companies, officers, agents, employees and independent conse suffered by customer resulting directly or indirectly from any services of the securacy of the information, errors occurring a companies, officers, agents, employees and independent consessuffered by customer resulting directly or indirectly from any services and independent consessuffered by customer resulting directly or indirectly from any services and independent consessuffered by customer resulting directly or indirectly from any services.		0	0	o	0
US EPA	elle de la constitución de la co	Toxic Release inventory database	0	0	0	0
STATE	UST/AST	Registered underground or	4	1	1	3
D) Databa	ises searched	to 1 mile:		4		
US EPA	ERNS	Emergency Response Notification System of spills	0	0	0	. 0
US EPA	GNRTR	RCRA registered small or large	0	1		
STATE	21,022		0	-1	0	<u>1</u>
SITTLE	OF ICEO	State apilia list				
NOTES			svided by VI.			
		9				
	<del></del>					






For More Information Call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403 Report ID: 1200S0021

Date of Report: February 2, 2000



For More Information Call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403 Report ID: 1200S0021 Date of Rep

Date of Report: February 2, 2000



For More Information Call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403


Report ID: 1200S0021

Date of Report: February 2, 2000

Page #5



#### Street Map



#### SITE INVENTORY

		9 (S (1)	No.	Α	(5	Si.	91.			B,					,	С	520	,	D.	-147. 200
MAP ID	PROPERTY AND THE ADJACENT. (within 1/8 mile)	VISTA ID DISTANCE DIRECTION	N.	CORRACTS(TSD)	Ids	SOIS	CERCLIS/NFRAP	TSD	LUST	SWLF	DEED RSTR	CORILISE	TOXIC PITS	WATER WELLS	PCRA VIOL	IRIS	JST/AST	ERNS	GNRTR	SPILLS
1	Capistrano Wholesale Nursery 29812 Ortega San Juan Capistra, ca 92675	1284439 0.00 MI NA	-		===					_==							x			
2	TALEGA LIFT STATION #2 31500 ORTEGA HY SAN JUAN CAPISTRANO, CA	4988387 0. <b>05 M</b> I E															x			
3	CHIQUITA WATER RECLAMATION PL 28793 ORTEGA HY SAN JUAN CAPISTRANO, CA	1284443 0.05 MI W															x			
3	CHIQUITA WATER RECLAMATION PL 28793 ORTEGA SAN JUAN CAPISTRANO, CA 92675	1178126 0.05 MI W															x			

				Α						B:			-		, na	C			Do	
MAP ID	) Di	/ISTA ID STANCE ECTION	7	CORRACTS(TSD)	SPL	10\$	CERCLIS/NFRAP	TSD	ISI	SWLF	DEED RSTR	CORTESE	TOXIC PITS	WATER WELLS	RCRA VIOL	IRIS	UST/AST	ERNS	GNRTR	SPILLS
4		497554 0.23 MI NE															х			
4	. 4.16 114.4.1	356626 0.24 MI E						x											x	



0.00			J) ş	A			.i., .s	Ç		В				× 1	S.07	C		183	D	
MAP ID	SITES IN THE SURROUNDING A (within 1/4 - 1/2 mile)	REA Vista id		RACTS(TSD)			CLIS/NFRAP				RSTR	TESE	C PITS	ER WELLS	4 VIOL	A PORTER OF	4ST		IR	8
		DISTANCE DIRECTION	를	CO	SPI	SC	CER	ISD	LUST	SWL	DEEL	COR	roxi	WAT	RCR/	IRIS	UST/	ERNS	GNR	
	RANCHO MISSION VIEJO 28672 ORTEGA SAN JUAN CAPISTRANO, CA 92675	1239230 0.48 MI E		==					x			x					x	-		

		9 OL 3	Ĭ.	Α			ýŽ.	y		В		- Yes	(A) (	95.30	: :30::	C	1 V	56	D	V.
MAP ID		VISTA ID DISTANCE DIRECTION	_	CORRACTS(TSD)	S.	SCI.	CERCLIS/NFRAP	ISD	tust	SWLF	DEED RSTR	CORTESE	TOXIC PITS	WATER WELLS	RCRA VIOL	IRIS	UST/AST	ERNS	GNRTR	SPILIS
6	FORSTER CANYON LANDFILL I-5 AT SAN JUAN CREEK ROAD SANTA ANA, CA 92701	5445794 0.82 Mi			\}					x										
6	FORSTER CANYON LANDFILL - CLOSED LA NOVA SAN JUAN CREEK RD. SAN JUAN CAPISTRANO, CA	5338285 0.82 MI	r							x					-					
6	FORSTER CANYON LANDFILL STN 17 FORSTER CANYON ROAD SAN JUAN CAPISTRANO, CA	4824755 0.82 MI			_					x										
7	MARBELLA GOLF COUNTRY CLUB 30650 GOLF CLUB DR SAN JUAN CAPISTRANO, CA 92675	1284450 0.88 Mi W	·														x			
7	MARBELLA GOLF COUNTRY CLUB 30650 GOLF CLUB SAN JUAN CAPISTRANO, CA 92675	4027920 0.88 MI W															x			
8	SIERRA SOILS 30921 LA PATA ROAD SAN JUAN CAPISTRANO, CA 92675	6831650 0.9 <b>5 M</b> I E								×										
9	ORTEGA CLEANERS 31654 RANCHO VIEJO RD STE F SAN JUAN CAPISTRANO, CA 92675	312315 0.95 MI SW																	x	
	SAN JUAN HILLS GOLF CLUBHOUSE 32120 SAN JUAN CREEK SAN JUAN CAPISTRANO, CA 92675	4042340 0.97 MI SW															x			
11	LA PATA ROAD GREENWASTE FACILITY 31748 LA PATA ROAD SAN JUAN CAPISTRANO, CA 92675	5338246 0.98 MI E	`							x										



THE STATE OF THE S	State of the state of	light:	A			i er		ï,	В		- 1, 1		; 47°		С		90.3	D	Ç. T
UNMAPPED SITES			CORRACTS(TSD)			CLIS/NFRAP				PSTR	TESE	C PITS	ER WELLS	VIOL.		AST		~	S
<b>第</b> 图 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	VISTA ID	NPL	COR	SPL	SCL	CERC	ISD	LUST	SWIF	DEED	COR	ž	WAT	RCR.	IRIS	ST/	N.	30	SPIL
SAN JUAN CAPISTRANO LANDFILL	7448295			C. P. C.															1 ,
NEAR SAN JUAN CREEK 300'N									Х	Ì		ı	•						
SAN JUAN CAPISTRANO, CA					,							J	ļ						•
RE ED RESERVOIR	4950373						_								_	*****			<b> </b>
LATITUDE 33-29-33N				Ì					ŀ	.		- 1					-	х	
SAN JUAN CAPISTRANO, CA 92675		.				Ì							1	1					
SAN JUAN CAPISTRANO (DIST. 12)	6612759													$\neg$					
SAN JUAN CAPISTRANO, CA	ļ		ı	- 1		j	ļ		İ					- 1	j	Х	- 1		
PROVINCIAL PROPERTIES DUMP	7431245		$\neg$				$\neg$		$\neg$			$\dashv$		-		寸			
UNKNOWN	- 1	- 1		ı					хİ		- 1	- [		- 1			- 1		
SAN JUAN CAPISTRANO, CA 92675	j	ı	- 1	Į		ł	İ			1	- 1			- 1		- 1			
PROVINCIAL PROPERTIES	6830417	Ť	_	寸	$\neg$	7	$\neg$	T		一	寸	7	寸	-		_	-+		$\neg$
SAN JUAN CAPISTRANO, CA	- 1			J	- 1			ļ	X	- 1			ı			- 1			
LOMAS SAN JUAN MODEL HOME SITE	4223107	7	$\neg$	T	_				7	$\dashv$	7	十	7	7	1	寸	_	$\dashv$	
TRACT 10139	ĺ	-		ļ	Ī			χ		- 1			i				ļ		
SAN JUAN CAPISTRANO, CA 92675			- [	- 1	-					-		- 1	ı		-	l			-



#### DETAILS

#### PROPERTY AND THE ADJACENT AREA (within 1/8 mile)

VISTA Address*:	29812	Trano Wholesa Ortega Jan Capistra, C			VISTA II Distand Plotted	ce/Direction	1284439 1: 0.00 Mi / Point	NA
STATE UST - S		lerground Storage		612	C. A.	jency iD:	N/A	
Agency Ad			SAME AS AE		2.7.7.4	40010 J. 101	11.44.6.4	
Undergrou	nd Tanks		1					
Abovegrou	ınd Tank:	s:	NOT REPOR	TED				İ
Tanks Rem	oved:		NOT REPORT	TED				
Tank ID:		T001U	· · · · · · · · · · · · · · · · · · ·	Tank Status:		OTHER		
Tank Conte	ents:	UNLEADED GAS		Leak Monitor	ina:	Agency Code	e (')	
Tank Age:		NOI REPORTED		Tank Piping:	<b>J</b> -	BARE STEEL		
Tank Size (l	Jnits):	550 (GALLONS)		Tank Materia	l:	BARE STEEL		ĺ

VISTA	TALEGA LIFT STAT	ON #2	VISTA ID#:	4988387	MapiD
Address*	31500 ORTEGA H		Distance/Direction:	0.05 MI / E	1362
20.0	SAN JUAN CAPIS		Plotted as:	Point	2
TATE UST -	State Underground St	grage Tank / SRC# 6438	EPA/Agency ID:	N/A	
Agency A	ddress:	SAME AS ABOVE			1
Undergrou	nd Tanks:	NOT REPORTED			
Abovegrou	und Tanks:	NOT REPORTED			
Tanks Rem	oved:	NOI REPORTED			

CS 1000 COSC 11 C C C C C C C C C C C C C C C C C	CHIQUITA WATER 28793 ORTEGA H SAN JUAN CAPIS		VISTA ID#: Distance/Direction Plotted as:	1.284443 n. 0.05 MI / W Point
STATE UST - :	State Underground St	orage Tank / SRC# 6438	EPA/Agency ID:	N/A
Agency A	ddress:	SAME AS ABOVE		
Undergrou	nd Tanks:	NOI REPORTED		
Abovegrou	ınd Tanks:	NOT REPORTED		

NOT REPORTED



Tanks Removed:

VISTA address includes enhanced city and ZIP.

For more information call VISTA information Solution

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 120050021 Version 2.6.1 Date of Report: February 2, 2000

Page #10

Map ID:

# PROPERTY AND THE ADJACENT AREA (within 1/8 mile) CONT.

VISTA	CHIQ	UITA WATER RECL	AMATION PL	VISTA ID#:		1178126
Adoress*:	28793	ORTEGA		Distance/I	Direction	0.05 MI / W
10 2 6 6 1 II	SAN	UAN CAPISTRANO	O. CA 92675	Plotted as		Point
STATE UST - S			Tank / SRC# 1612	EPA/Agen	cv:ID:	N/A
Agency Ad	ddress:		CHIQUITA WATER RECLAMAT 28793 ORTEGA SAN JUAN CAPISTRA, CA 926 6	ION PL		
Abovegrou	ınd Tanl	<s:< td=""><td>NOI REPORTED</td><td></td><td></td><td></td></s:<>	NOI REPORTED			
Tanks Rem	oved:		NOT REPORTED			
Tank ID:		T001U	Tank Status:	AC	TIVE/IN SERI	/ICE
Tank Conte	ents:	DIESEL	Leak Monito		ency Code	<i>(</i> )
Tank Age:		NOT REPORTED	Tank Piping:	•	RE STEEL	
Tank Size (U	Jnits):	4000 (GALLONS)	Tank Materi		ERGLASS	
Tank ID:		1001U	Tank Status:		TIVE/IN SERV	IICE
Tank Conte	nts:	UNLEADED GAS	Leak Monito	rina: <i>Age</i>	ency Code .	(°)
Tank Age:		NOT REPORTED	Tank Piping:	•	RE STEEL	•
Tank Size (U	Inits):	4000 (GALLONS)	Tank Materia		RGLASS	
Tank ID:		T001U	Tank Status:		TIVE/IN SERV	ICE
Tank Conte	rits:	PETROLEUM	Leak Monito	ring: Age	ency Code i	··)
Tank Age:		NOT REPORTED	Tank Piping:	_	E STEEL	
Tank Size (U	inits):	550 (GALLONS)	Tank Materia	al: <i>FIBE</i>	RGLASS	
Tank ID:		T001U	Tank Status:	ACI	IVE/IN SERV	ICE
Tank Conte	nts:	DIESEL	Leak Monito	rina: Age	ncy Code (	·· <i>y</i>
Tank Age:		NOI REPORTED	Tank Piping:	•	E STEEL	
Tank Size (U	nits):	2500 (GALLONS)	Tank Materia	il: FIBE	RGLASS	
Tank ID:		T001U	Tank Status:	ACI	IVE/IN SERV	ICE
Tank Conter	nts:	PETROLEUM	Leak Monito	rina: <i>Age</i>	ncy Code (	·
Tank Age:		NOT REPORTED	Tank Piping:	-	E STEEL	
Tank Size (Uı	nits):	550 (GALLONS)	Tank Materia	l: FIBER	RGLASS	
Tank ID:		T001U	Tank Status:		VE/IN SERVI	CE
Tank Conten	its:	DIESEL	Leak Monitor		ncy Code (	
Tank Age:		NOT REPORTED	Tank Piping:	•	STEEL	•
Tank Size (Ur	nits):	1000 (GALLONS)	Tank Materia	• FIBER	RGLASS	



\* VISTA address includes enhanced city and ZIP.
For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 120050021 Version 2.6.1

Date of Report: February 2, 2000

Page #11

MapiD

### SITES IN THE SURROUNDING AREA (within 1/8 - 1/4 mile)

Address*:	CASPER REGIONAL P. 33401 ORTEGA SAN JUAN CAPISTRAI	Dist	TA ID#: tance/Direction; tted as:	3497554 0.23 Mt / NE Point	Ma
	ate Underground Storag	THE PARTY OF THE P	V/Agency ID:	N/A	
Agency Address:		CASPER REGIONAL PARK 33401 ORTEGA SAN JUAN CAPISTRA, CA 92675	, , , , , , , , , , , , , , , , , , ,	(NOTE OF THE PROBLEMS OF	
Underground	l Tanks:	2			
Abovegroun	d Tanks:	NOT REPORTED	NOT REPORTED		
Tanks Remov	red:	NOT REPORTED			
Tank ID:	7001Ú	Tank Status:	ACTIVE/IN SERV	ICE	ĺ
fank Conten	ts: UNLEADED GAS	Leak Monitoring:	Agency Code	(*)	
ĭank Age:	NOT REPORTED	Tank Piping:	FIBERGLASS		
Tank Size (Un	its): 1000 (GALLONS)	Tank Material:	BARE STEEL		
fank ID:	1001U	Tank Status:	ACTIVE/IN SERV	TICE	†
Tank Content	S: DIESEL	Leak Monitoring:	Agency Code	~)	
fank Age:	NOT REPORTED	Tank Piping:	FIBERGLASS	-	
Tank Size (Un	its): 500 (GALLONS)	Tank Material:	BARE STEEL		

VISTA	FORD MOTOR CO		VISTA ID#:	5356626
Address*:	33600 ORTEGA HV	NY TSD SITE	Distance/Direction	0.24 MI / E
TOWARD P	SAN JUAN CAPISTI	RANO, CA 92675	Plotted as:	Point :
RCRA-SmGe	en - RCRA-Small Gene	rator / SRC# 6379	EPA-ID:	CAD981393085
Agency Ad	ddress:	SAME AS ABOVE		
Generator	Class:		nth but less than 1000 kg./month o	of non-acutely hazardou
		<u>waste</u>		
RCRA-TSD /	SRC# 6379	<u>waste</u>	EPA ID:	CAD981393085
RCRA-TSD / Agency Ac	<del></del>	SAME AS ABOVE	EPA ID:	CAD981393085
Agency Ac	<del></del>		EPA ID:	CAD981393085
Agency Ac Off-Site Wa	idress: ste Received:	SAME AS ABOVE	EPA ID:	CAD981393085
Agency Ac	ldress: ste Received: sal:	SAME AS ABOVE NO	EPA ID:	CAD981393085

# SITES IN THE SURROUNDING AREA (within: 1/4 - 1/2 mile)

VISTA RANCHO MISSIO	N VIEJØ	VISTA ID#:	1239230		Mapil
Address*: 28672 ORTEGA		Distance/Direction	0.48 MI / E		
SAN JUAN CAPIS	IRANO, CA 92675	Plotted as:	Point	<u></u>	5
STATE UST - State Underground St	orage Tank / SRC# 1612	EPA/Agency ID:	N/A		L
Agency Address:	RANCHO MISSION VIEIC 28672 ORIEGA SAN JUAN CAPISTRA, CA		······································		
Underground Tanks:	1				
Aboveground Tanks:	NOI REPORTED			i	
Tanks Removed:	NOI REPORTED				



\* VISTA address includes enhanced city and ZIP.
For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 1200S0021 Version 2.6.1

Date of Report: February 2, 2000

Page #12

Map ID

# SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.

Tank ID: 1001U	Tank Status: CLOSED REMOVED
Tank Contents: UNKNOWN	Leak Monitoring: Agency Code (*)
Tank Age: NOT REPORTED	<b>3</b>
Tank Size (Units): 500 (GALLONS)	Tank Piping: BARE STEEL Tank Material: BARE STEEL
CORTESE / SRC# 4840	
Agency Address:	Agency ID: 9UT2195
List Name:	LEAKING TANK
Site ID:	9UT2195
	Storage Tank / SRC# 6351 EPA/Agency ID: N/A
Agency Address:	RANCHO MISSION VIEJO 28672 ORTEGA HWY
Facility ID:	SAN JUAN CAPISTRANO, CA 92675 9UT2195
Leak Report Date:	03/18/92
Site Assessment Plan Submitted:	12/13/92
Contamination Confirmed Date:	03/18/92
Remediation Plan Date:	05/24/93
Leak Cause:	UNKNOWN
Leak Source:	UNKNOWN .
Substance:	GASOLINE
Remediation Event:	EXCAVATE AND DISPOSE
Remediation Event:	ENFORCEMENT: NONE TAKEN
Remediation Status:	REMEDIATION PLAN SUBMITTED
Media Affected:	SOIL ONLY
Lead Agency:	LOCAL AGENCY (COUNTY)
Description / Comment:	BENEFICIAL: MUNICIPAL GROUNDWATER USELOCASENUM: 92UT48,BASINNUM:901.28.GWDEP1H:
STATE LUST - State Leaking Underground St	
Agency Address:	RANCHO MISSION VIEJO 28675 ORTEGA HWY SAN JUAN CAPISTRANO, CA 92675
Facility ID:	92U148
Substance:	GASOLINE
Remediation Event:	ACTION TAKEN BY RP
Media Affected:	GROUNDWAIER
Lead Agency:	LOCAL
Funding:	FEDERAL
Description / Comment:	REFERRED: NOT REFERRED TO REGIONALSITE OPEN: YES
STATE LUST - State Leaking Underground Sta	
Agency Address:	RANCHO MISSION VIEJO 28672 ORTEGA HWY SAN JUAN CAPISTRANO, CA 92675
Facility ID:	9UT2195
Leak Report Date:	03/18/92
Site Assessment Plan Submitted:	12/13/92
Contamination Confirmed Date:	03/18/92
Remediation Plan Date:	05/24/93
Substance:	GASOLINE
Remediation Event:	EXCAVAIE AND DISPOSE



\* VISTA address includes enhanced city and ZIP.
For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 120050021 Version 2.6.1

Date of Report: February 2, 2000 Page #13

# SITES IN THE SURROUNDING AREA (within 1/4 - 1/2 mile) CONT.

Remediation Status:	REMEDIATION PLAN SUBMITTED
Media Affected:	SOIL ONLY
Lead Agency:	LOCAL AGENCY
Region / District:	SAN DIEGO REGION
Description / Comment:	COUNTY: ORANGEXSTREET:REVIEW DATE:

#### SITES IN THE SURROUNDING AREA (within 1/2 - 1 mile)

VISTA	FORSTER CANYON LANDFILL I-5 AT SAN JUAN CREEK ROAD		VISTA ID#:	5445794	
Address*:			Distance	0.82 MI	
	SANTA ANA, CA 92701		Plotted as:	Polygon	
WMUDS / SR			Agency ID:	9 000000586	
Agency Address: Solid Waste Inventory System ID:		FORSIER CANYON LANDF. I-5 AT SAN JUAN CREEK RC SAN JUAN CAPISTRANO, C	ILL DAD		
		30-AB-0366		•	
Facility Typ	e:	SOLID WASTE SITES-CLASS	ili - Landfilis for nonhazardo	us solid wastes.	
Facility In S System:	tate Board Waste Discharger	NO .			
Chapter 15	Facility:	NO			
Solid Waste	Assessment Test Facility:	NO			
Toxic Pits C	leanup Act Facility:	NO			
RCRA Facili	ity:				
Department of Defense Facility:		NO			
Open To Pu	blic:	NO 1 MAJOR THREAT TO WATER QUALITY			
Number Of	Waste Management Units:				
Threat To W	ater:				
Complexity:  Facilty Status:  Waste 1 (Nature/Type):  Waste 2 (Nature/Type):  Rank:		Category B - Any facility having a physical, chemical or biological waste treatment system (except for septic systems with subsurface disposal), or any Clallor III disposal site, or facilities without treatment systems that are complex, such mannas with petroleum products, solid wastes, and sewage pump out facilities. ACTIVE - Any facility with a continuous or seasonal discharge that is under Waste Discharge Requirements. Those facilities that are not under Waste Discharge Requirements (WURDs) are coded as ACTIVE when: 1) there is an active enforcement order for the facility, 2) there is a significant violation that has not been resolved to the satisfaction of the Regional Board, 3) after an inspection further action is required to mitigate a problem at the facility, or 4) there is some problem that the Regional Board considers significant enough to warrant classification as an ACTIVE facility.  NONHAZARDOUS SOLID WASTES - Influent or solid wastes that contain nonhazardous putrescible and nonputrescible solid, semisolid, and liquid wastes (e.g. garbage, trash, refuse, paper, demolition and construction wastes, manure, vegetable or animal solid and semisolid wastes)." / "SOLID WASTES"			
					NOT REPORTED
		Enforcemen	ts At Facility:	NO	
Violations At	t Facility:	YES			



\* VISTA address includes enhanced city and ZIP.
For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 1200S0021

Version 2.6.1

Date of Report: February 2, 2000

Page #14

## SITES IN THE SURROUNDING AREA (within 1/2 - 1 mile) CONT.

VISTA	FORSTER CANY	ON LANDFILL - CLOSED	VISTA ID#:	5338285
Address*:	LA NOVA SAN	JUAN CREEK RD.	Distance	0.82 MI
	SAN JUAN CAP		Plotted as:	Polygon
	<ul> <li>Solid Waste Land!</li> </ul>	III / SRC# 6544	Agency ID:	30-AB-0366
Agency Ad	ddress:	SAME AS ABOVE		
Facility Typ	e:	SOLID WASTE DISPOSAL	FACILITY	
Facility Sta	tus:	CLOSED		
Facility Life	:	NOI REPORTED		
Permit Stati	us:	OTHER	·	
Waste:		<b>OTHER</b>		

VISTA	FORSTER CANYON LANDFILL STN 17 FORSTER CANYON ROAD		VISTA ID#	4824755		
Address*:			Distance	0.82 MI		
	SAN JUAN CAPISTRANO,	25555 WE 3555 NOT SEE 1	Plotted as:	Polygon		
WMUDS / SR			Agency ID:	9 000036N90		
Agency A	ddress:	SAME AS ABOVE		. [2.5444.55]		
Solid Waste	e Inventory System ID:	NOT REPORTED				
Facility Type: Facility In State Board Waste Discharger System: Chapter 15 Facility:		SOLID WASTE SITES-CLA	ASS III - Landfills for nonhazardo	ous solid wastes.		
		NO				
		NO				
Solid Waste	e Assessment Test Facility:	NO	•			
Toxic Pits C	leanup Act Facility:	NO .				
RCRA Facility: Department of Defense Facility:		NO NO				
						Open To Pu
Number Of	Waste Management Units:	1				
Threat To W	ater:	MODERATE THREAT TO WATER QUALITY				
Complexity:  Can tree Horizontal Facility Status:  Facility Status		treatment system (exce for ill disposal site, or fa marinas with petroleum HISTORICAL - Any regum WDRs or consciously all not under Waste Discha the Regional Board con- activities unnecessary a	y having a physical, chemical ept for septic systems with subs cilities without treatment system products, solid wastes, and se ated facility for which the Regi lowed an NPOS permit to expi prige Requirements (WURDs) manders with the facility any unregulated of the facility any unregulated the facil	urface disposal), or any Class ms that are complex, such as ewage pump out facilities, ional Board has rescinded all re. Those facilities that are ay be set to HISTORY when ionitoring or compliance		
Waste 1 (Na Waste 2 (Na	ature/Type):	nonhazardous 'putrescii (e.g. garbage, trash, reli	D WASTES - Influent or solid was ble and nonputrescible solid, s fuse, paper, demolition and co lid and semisolid wastes)."/"S(	semisolid, and liquid wastes		
Rank:		NOT REPORTED				
Enforcements At Facility:		NO				
Violations A	-	NO				



\* VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 120050021

Version 2.6.1

Date of Report: February 2, 2000 Page #15

Map ID

6

Map ID

## SITES IN THE SURROUNDING AREA (within 1/2 - 1 mile) CONT.

Address:	MARBELLA GOLF CO 30650 GOLF CLUB DI SAN JUAN CAPISTRA	₹	VISTA ID#: Distance/Directi Plotted as:	1284450 On: 0.88 MI / W. Point
TATE UST - S	State Underground Storag	ge Tank / SRC# 6438	EPA/Agency ID:	NZA
Agency Address:		MARBELLA GOLF COUN 30650 GOLF CLUB DR SAN JUAN CAPISTRANO	TIRY CLUB	
Undergroui	nd Tanks:	NOT REPORTED		
Abovegrou	ınd Tanks:	NOT REPORTED		
Tanks Rem	oved:	NOT REPORTED		

VISTA N	IARBELLA GOLF CO	DUNTRY CLUB	Estimate No.	VISTA ID#:	4027920	
Address*: 3	0650 GOLF CLUB		1	Distance/Direction	0.88 MI / W	
S	AN JUAN CAPISTRA	NO, CA 92675	HARMAN MAKES COURT DOWN TO THE RES	Plotted as:	Point	
TATE UST - Stat	e Underground Storag	je Tank / SRC# 1	612	PA/Agency ID:	N/A	
Agency Addr	,	30650 GOLI	GOLF COUNTRY CLU F CLUB CAPISTRA, CA 92675	В		
Aboveground	Tanks:	NOT REPOR	NOI REPORTED			
Tanks Remove	ed:	NOT REPOR	TED			
Tank ID:	U001U		Tank Status:	NOT AVAILABLE		
Tank Contents	NOT AVAILABLE		Leak Monitorin	a: UNKNOWN		
Tank Age:	NOI REPORTED		Tank Piping:	NOI AVAILABLI	<u> </u>	
Tank Size (Unit	s): NOT REPORTED (NO	OT AVAILABLE)	Tank Material:	NOT AVAILABLE	·	

		- idini matci	1001	
VISTA SIERRA SOILS Address*: 30921 LA PATA R SAN JUAN CAPIS	Market and the second s	<b>7/5</b>	VISTA ID#: Distance/Direction Plotted as:	6831650 on: 0.95 MI / E Point
STATE SWLF - Solid Waste Landfill	/ SRC# 6544		Agency ID:	30-AB-0372
Agency Address:	SAN JUA	OILS N PATA ROAD N CAPISTRANO, CA STING FACILITY		
Facility Type: Facility Status:	ACTIVE	SINVE PACILITY		
raciiity status:	ALIIVE			

Facility Status:	ACTIVE	!
Facility Life:	NOT REPORTED	
Permit Status:	PERMITTED/LICENSED	
Waste:	ANIMALS (WASTE BODIES)	

VISTA ORTEGA CLEANER Address* 31654 RANCHO V SAN JUAN CAPIST	IEJO RD STE F	VISTA ID#:  Distance/Direction: Plotted as:	312315 0.95 MI / SW Point	Мар ID <b>9</b>
RCRA-SmGen - RCRA-Small Gen		EPA ID:	CAD982029530	
Agency Address:	SAME AS ABOVE		10, (0002020000	İ
Generator Class: Generates 100 kg./month but less than 1000 kg./month of non-acutely hazardous				



VISTA address includes enhanced city and ZIP.

For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 1200S0021

Version 2.6.1

Date of Report: February 2, 2000

Page #16

Map ID

## SITES IN THE SURROUNDING AREA (Within 1/2 - 1 mile) CONT.

Address*: 3212	Juan Hills Golf D San Juan Creek Juan Capistrano	(	Dista	VID#: nce/Direction ad as:		м <sub>ар Ю</sub>
STATE UST - State Ui	derground Storage	Tank / SRC# 1612	EPA7	Agency ID:	N/A	Jan Contract
Agency Address: Underground Tank		SAN JUAN HILLS GOLF CLI 32120 SAN JUAN CREEK SAN JUAN CAPISTRA, CA 1	,			
Aboveground Tanks:		NOT REPORTED				
Tanks Removed:		NOT REPORTED			•	1
Tank ID:	U001U	Tank Stat	 Us:	ACTIVE/IN SER	VICE	
Tank Contents:	UNLEADED GAS	Leak Moi	nitorina:	Agency Code	<i>(</i> )	
Tank Age:	NOT REPORTED	Tank Pipi	-	BARE STEEL		
Tank Size (Units):	2000 (GALLONS)	Tank Mat	•	<b>FIBERGLASS</b>		

Tank Size (	OTHIS): LOGO (C. ILLE	lank Ma	terial: FIBERGLASS	
VISTA	LA PATA ROAD	GREENWASTE FACILITY	VISTA ID#:	5338246
Address*: 31748 LA PATA RO		OAD	Distance/Direction	0.98 MI / E
		TRANO, CA 92675	Plotted as:	Point
TATE SWLF	- Solid Waste Landfill	/ SRC# 6544	Agency ID:	30-AB-0364
Agency Ad		LA PATA ROAD GREENWA 31748 LA PATA ROAD SAN JUAN CAPISTRANO, ( COMPOSTING FACILITY		
Facility Stat	tus:	ACTIVE		
Facility Life		NOT REPORTED		
Permit Statı	ıs:	PERMITTED/LICENSED		
Waste:		MIXED WASTE		



Report ID: 1200\$0021 Version 2.6.1

Date of Report: February 2, 2000
Page #17

MapID

### UNMAPPED SITES

VISTA SAN JUAN CAPISTRANC		LANDFILL	VISTA ID#:	7448295
Address*;	NEAR SAN JUAN CREEK 30 SAN JUAN CAPISTRANO,	AND THE RESERVE OF THE PARTY OF		
WMUDS / SF	RC# 5857		Agency ID:	9:300005NUR
Agency A	ddress:	SAME AS ABOVE		The second secon
Solid Waste	e Inventory System ID:	NOT REPORTED		
Facility Typ	oe:	Not reported		
Facility In S	State Board Waste Discharger	NO		
System:	-			
Chapter 15	5 Facility:	NO		
Solid Waste	e Assessment Test Facility:	NO		
Toxic Pits C	Cleanup Act Facility:	NO		
<b>RCRA Facil</b>	lity:	NO		
Departmen	nt of Defense Facility:	NO	•	
Open To Pu	ublic:	NO		
Number Of	Waste Management Units:	7		
Rank:		NOI REPORTED		
Enforceme	nts At Facility:	NO .		
Violations A		NO		

VISTA	PROVINCIAL PROPERTIES	DUMP	VISTA ID#:	7431245
Address*:				
VMUDS / SR	C# 5857		Agency ID:	9 300002NUR
Адепсу А	ddress:	SAME AS ABOVE		
Solid Waste	e Inventory System ID:	NOT REPORTED		
Facility Typ	oe:	Not reported		
Facility In S System:	State Board Waste Discharger	NO		
Chapter 15	Facility:	NO		
Solid Waste	Assessment Test Facility:	NO		
Toxic Pits C	leanup Act Facility:	NO		
RCRA Facil	ity:	NO		
	nt of Defense Facility:	NO		
Open To Pu		NO		
Number Of	Waste Management Units:	1		
₹ank:		NOI REPORTED		
Enforceme	nts At Facility:	NO		
Violations A	At Facility:	NO		



\* VISTA address includes enhanced city and ZIP.
For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403. Report ID: 1200\$0021 Version 2.6.1

Date of Report: February 2, 2000 Page #18

### UNMAPPED SITES CONT.

VISTA PROV	ICIAL PROPERTIES VISTA ID#: 6830417
Address*:  SAN.J	AN CAPISTRANO, CA
STATE SWLF - Solid V	ste Landfill / SRC# 6544 Agency ID: 30-CR-0053
Agency Address:	SAME AS ABOVE
Facility Type:	SOLID WASTE DISPOSAL FACILITY
<b>Facility Status:</b>	OTHER
Permit Status:	UNDER REVIEW

VISTA	LOMAS SAN JUAN MO	DDEL HOME SITE	VISTA ID#:	14223107		
Address*:	TRACT 10139		수 수 보기 있다.			
	SAN JUAN CAPISTRAN	NO, CA 92675				
STATE LUST -	State Leaking Undergroun		51 EPA/Agency ID:	N/A		
Agency Ad	idress:	SAME AS ABOVE				
Facility ID:		9UT197				
Leak Date:		04/12/85		•		
Leak Repor	t Date:	04/23/85				
Site Assessn	ment Plan Submitted:	04/23/85		\		
Site Assessn	nent Began:	10/30/85				
<b>Pollution Ch</b>	naracterization Date:	07/14/86				
Remediatio	n Plan Date:	09/29/86		· · · · · · · · · · · · · · · · · · ·		
Case Close	d Date:	12/11/91				
Leak Detec	tion Method:	OTHER MEANS				
Leak Cause		UNKNOWN				
Leak Source	9:	UNKNOWN				
Substance:		GASOLINE				
Remediation	n Event:	EXCAVATE AND TREAT				
Remediation	n Event:	LEAK STOPPED BY: OTHER M	MEANSENFORCEMENT: NONE	TAKEN		
Remediation	n Status:	CASE CLOSED				
Media Affec	ted:	AQUIFER (MUNICIPAL USE)				
Lead Agenc	:у:	LOCAL AGENCY (COUNTY)	)			
Description A		85UT40,BASINNUM:901,27,0	ROUNDWATER USELOCASENL GWDEPTH: 6.8"	iM: .		
	tate Leaking Undergroun	d Storage Tank / SRC# 654	5 EPA/Agency ID:	N/A		
Agency Add	dress:	SAME AS ABOVE				
Facility ID:		901197		•		
Leak Report	Date:	04/23/85				
Site Assessm	ent Plan Submitted:	04/23/85		***		
Site Assessm	ent Began:	10/30/85		· · · · · · · · · · · · · · · · · · ·		
Pollution Cha	aracterization Date:	07/14/86				
Remediation	ı Plan Date:	09/29/86	V	····		
Case Closed	Date:	12/11/91				
Substance:		GASOLINE		-		
Remediation	Event:	EXCAVATE AND TREAT	——————————————————————————————————————			
Remediation	Status:	CASE CLOSED				
Media Affect	ted:	AQUIFER (MUNICIPAL USE)				



\* VISTA address includes enhanced city and ZIP.
For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 1200S0021 Version 2.6.1

Date of Report: February 2, 2000
Page #19

# UNMAPPED SITES CONT.

Lead Agency:	LOCAL AGENCY
Region / District:	SAN DIEGO REGION
Description / Comment:	COUNTY: ORANGEXSTREET: LA NOVIA AVENUEREVIEW DATE:



# SITE ASSESSMENT PLUS REPORT (ALL DATABASES SEARCHED TO 1 MILE)

#### DESCRIPTION OF DATABASES SEARCHED

#### A) DATABASES SEARCHED TO 1 MILE

NPL SRC#: 6476 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for NPL was November, 1999.

The National Priorities List (NPL) is the EPA's database of uncontrolled or abandoned hazardous waste sites identified for priority remedial actions under the Superfund program. A site must meet or surpass a predetermined hazard ranking system score, be chosen as a state's top priority site, or meet three specific criteria set jointly by the US Dept of Health and Human Services and the US EPA in order to become an NPL site.

SPL SRC#: 6282 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Calsites Database: Annual Workplan Sites was July, 1999.

This database is provided by the Cal. Environmental Protection Agency, Dept. of Toxic Substances Control. The agency may be contacted at: 916-323-3400.

CORRACTS SRC#: 6379 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for HWDMS/RCRIS was September, 1999.

The EPA maintains this database of RCRA facilities which are undergoing "corrective action". A "corrective action order" is issued pursuant to RCRA Section 3008 (h) when there has been a release of hazardous waste or constituents into the environment from a RCRA facility. Corrective actions may be required beyond the facility's boundary and can be required regardless of when the release occurred, even if it predates RCRA.

#### B) DATABASES SEARCHED TO 1 MILE

CERCUS SRC#: 6474 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for CERCLIS was October, 1999.

The CERCLIS List contains sites which are either proposed to or on the National Priorities List(NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL. The information on each site includes a history of all pre-remedial, removal and community relations activities or events at the site, financial funding information for the events, and unrestricted enforcement activities.



Cal Cerclis SRC#: 2462 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Ca Cerclis w/Regional Utility Description was June, 1995.

This database is provided by the U.S. Environmental Protection Agency, Region 9. The agency may be contacted at: . These are regional utility descriptions for California CERCLIS sites.

NFRAP SRC#: 6475 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for CERCLIS-NFRAP was October, 1999.

NFRAP sites may be sites where, following an initial investigation, no contamination was found, contamination was removed quickly, or the contamination was not serious enough to require Federal Superfund action or NPL consideration.

SCL SRC#: 6281 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Calsites Database: All Sites except Annual Workplan Sites (incl. ASPIS) was July, 1999.

This database is provided by the Department of Toxic Substances Control. The agency may be contacted at: .

The CalSites database includes both known and potential sites. Two-thirds of these sites have been classified, based on available information, as needing "No Further Action" (NFA) by the Department of Toxic Substances Control. The remaining sites are in various stages of review and remediation to determine if a problem exists at the site. Several hundred sites have been remediated and are considered certified. Some of these sites may be in long term operation and maintenance.

RCRA-TSD SRC#: 6379 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for HWDMS/RCRIS was September, 1999.

The EPA's Resource Conservation and Recovery Act (RCRA) Program identifies and tracks hazardous waste from the point of generation to the point of disposal. The RCRA Facilities database is a compilation by the EPA of facilities which report generation, storage, transportation, treatment or disposal of hazardous waste. RCRA TSDs are facilities which treat, store and/or dispose of hazardous waste.

SWLF SRC#: 5945 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for City of Los Angeles Landfills was April, 1999.

This database is provided by the City of Los Angeles, Environmental Affais Department. The agency may be contacted at: 213-580-1070.



#### **SWLF** SRC#: 6544

VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Ca Solid Waste Information System (SWIS) was November, 1999.

This database is provided by the Integrated Waste Management Board. The agency may be contacted at: 916-255-4021.

The California Solid Waste Information System (SWIS) database consists of both open as well as closed and inactive solid waste disposal facilities and transfer stations pursuant to the Solid Waste Management and Resource Recovery Act of 1972, Government Code Section 2.66790(b). Generally, the California Integrated Waste Management Board learns of locations of disposal facilities through permit applications and from local enforcement agencies.

#### Orange County Landfill SRC#: 6433

VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Orange County Landfills was April, 1999.

This database is provided by the Orange County Health Care Agency. The agency may be contacted at: 714-834-3446.

#### WMUDS SRC#: 5857

VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Waste Management Unit Database System (WMUDS) was February, 1999.

This database is provided by the State Water Resources Control Board. The agency may be contacted at: 916-892-0323. This is used for program tracking and inventory of waste management units. This system contains information from: Facility, Waste Management Unit, SWAT Program and Report Summary Information, Chapter 15 (formerly Subchapter 15). TPCA and RCRA Program Information, Closure Information; also some information from the WDS (Waste Discharge System).

The WMUDS system also accesses information from the following databases from the Waste Discharger System (WDS): Inspections, Violations, and Enforcements. The sites contained in these databases are subject to the California Code of Regulations - Title 23. Waters.

#### LUST SRC#: 5873

VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Region #9-SLIC List was August, 1996.

This database is provided by the Regional Water Quality Control Board, Region #9. The agency may be contacted at: 619-467-2980.

#### **LUST RG6** SRC#: 6275

VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Lahontan Region LUST List was August, 1999.

This database is provided by the Lahontan Region Six South Lake Tahoe. The agency may be contacted at: 530-542-5400.

#### LUST SRC#: 6277

VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Region #8-SLIC List was July, 1999.

This database is provided by the Regional Water Quality Control Board, Region #8. The agency may be contacted at: 909-782-4499.



Version 2.6.1

LUST RG9 SRC#: 6351 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Region #9 Leaking Underground Storage Tank List was August, 1999.

This database is provided by the Regional Water Quality Control Board, Region #9. The agency may be contacted at: 619-467-2980.

LUST SRC#: 6540 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Orange County-Groundwater Cleanup Program was September, 1999.

This database is provided by the Orange County Health Care Agency. The agency may be contacted at: 714-834-3446.

LUST RG8 SRC#: 6542 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Region #8-Santa Ana Regional Underground Tank Database List was October, 1999.

This database is provided by the Regional Water Quality Control Board, Region #8. The agency may be contacted at: 909-782-4499.

LUST SRC#: 6545 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Lust Information System (LUSTIS) was October, 1999.

This database is provided by the California Environmental Protection Agency. The agency may be contacted at: 916-445-6532.

CORTESE SRC#: 4840 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Cortese List-Hazardous Waste Substance Site List was April, 1998.

This database is provided by the Office of Environmental Protection, Office of Hazardous Materials. The agency may be contacted at: 916-445-6532.

The California Governor's Office of Planning and Research annually publishes a listing of potential and confirmed hazardous waste sites throughout the State of California under Government Code Section 65962.5. This database (CORTESE) is based on input from the following: (1)CALSITES-Department of Toxic Substances Control, Abandoned Sites Program Information Systems; (2)SARA Title III Section III Toxic Chemicals Release Inventory for 1987, 1988, 1989, and 1990; (3)FINDS; (4)HWIS-Department of Toxic Substances Control, Hazardous Waste Information System. Vista has not included one time generator facilities from Cortese in our database.; (5)SWRCB-State Water Resources Control Board; (6)SWIS-Integrated Waste Management Control Board (solid waste facilities); (7)AGT25-Air Resources Board, dischargers of greater than 25 tons of criteria pollutants to the air; (8)A1025-Air Resources Board, dischargers of greater than 10 and less than 25 tons of criteria pollutants to the air; (9)LTANK-SWRCB Leaking Underground Storage Tanks; (10)UTANK-SWRCB Underground tanks reported to the SWEEPS systems; (11) IUR-Inventory Update Rule (Chemical Manufacturers); (12) WB-LF- Waste Board -Leaking Facility, site has known migration; (13)WDSE-Waste Discharge System -Enforcement Action; (14)DTSCD-Department of Toxic Substance Control Docket.



For more information call VISTA Information Solutions, Inc. at 1 - 800 - 767 - 0403.

Report ID: 120050021

Date of Report: February 2, 2000

Version 2.6.1

#### Deed Restrictions SRC#: 1703

VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Deed Restriction Properties Report was April, 1994.

This database is provided by the Department of Health Services-Land Use and Air Assessment. The agency may be contacted at: 916-255-2014. These are voluntary deed restriction agreements with owners of property who propose building residences, schools, hospitals, or day care centers on property that is "on or within 2,000 feet of a significant disposal of hazardous waste".

California has a statutory and administrative procedure under which the California Department of Health Services (DHS) may designate real property as either a "Hazardous Waste Property" or a "Border Zone Property" pursuant to California Health Safety Code Sections 25220-25241. Hazardous Waste Property is land at which hazardous waste has been deposited, creating a significant existing or potential hazard to public health and safety. A Border Zone Property is one within 2,000 feet of a hazardous waste deposit. Property within either category is restricted in use, unless a written variance is obtained from DHS. A Hazardous Waste Property designation results in a prohibition of new uses, other than a modification or expansion of an industrial or manufacturing facility on land previously owned by the facility prior to January 1, 1981. A Border Zone Property designation results in prohibition of a variety of uses involving human habitation, hospitals, schools and day care center.

#### Toxic Pits SRC#: 2229

VISTA conducts a database search to identify all sites within 1 mile of your property.

The agency release date for Summary of Toxic Pits Cleanup Facilities was February, 1995.

This database is provided by the Water Quality Control Board, Division of Loans Grants. The agency may be contacted at: 916-227-4396.

# Water Wells SRC#: 5384

VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for USGS WATER WELLS was March, 1998.

The Ground Water Site Inventory (GWSI) database was provided by the United States Geological Survey (USGS). The database contains information for over 1,000,000 wells and other sources of groundwater which the USGS has studied, used, or otherwise had reason to document through the course of research. The agency may be contacted at 703-648-6819.

#### C) DATABASES SEARCHED TO 1 MILE

RCRA-Viols/Enf VISTA conducts a database search to identify all sites within 1 mile of your property.

The agency release date for HWDMS/RCRIS was September, 1999.

The EPA's Resource Conservation and Recovery Act (RCRA) Program identifies and tracks hazardous waste from the point of generation to the point of disposal. The RCRA Facilities database is a compilation by the EPA of facilities which report generation, storage, transportation, treatment or disposal of hazardous waste. RCRA Violators are facilities which have been cited for RCRA Violations at least once since 1980. RCRA Enforcements are enforcement actions taken against RCRA violators.



UST's SRC#: 1612 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Underground Storage Tank Registrations Database was January, 1994.

This database is provided by the State Water Resources Control Board, Office of Underground Storage Tanks. The agency may be contacted at: 916-227-4364; Caution-Many states do not require registration of heating oil tanks, especially those used for residential purposes.

UST's SRC#: 5498 VISTA conducts a database search to identify all sites within 1 mile of your property.

The agency release date for Fullerton Underground Storage Tank List was December,
1998.

This database is provided by the Fullerton Fire Department. The agency may be contacted at: 714-738-3160; Caution-Many states do not require registration of heating oil tanks, especially those used for residential purposes.

UST's SRC#: 6239 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for City of Anaheim UST Listing was July, 1999.

This database is provided by the City of Anaheim. The agency may be contacted at: 714-765-4049; Caution-Many states do not require registration of heating oil tanks, especially those used for residential purposes.

UST's SRC#: 6243 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for City of Orange Underground Storage Tank List was July, 1999.

This database is provided by the City of Orange Fire Department. The agency may be contacted at: 714-288-2541; Caution-Many states do not require registration of heating oil tanks, especially those used for residential purposes.

UST's SRC#: 6355

VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Santa Ana City UST List was September, 1999.

This database is provided by the City of Santa Ana Fire Department. The agency may be contacted at: 714-647-5761; Caution-Many states do not require registration of heating oil tanks, especially those used for residential purposes.

UST's SRC#: 6438 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Orange County Underground Tank Facilities was October, 1999.

This database is provided by the Orange County Health Care Agency. The agency may be contacted at: 714-834-3446; Caution-Many states do not require registration of heating oil tanks, especially those used for residential purposes.

AST's SRC#: 5513 VISTA conducts a database search to identify all sites within 1 mile of your property.

The agency release date for Aboveground Storage Tank Database was December, 1998.

This database is provided by the State Water Resources Control Board. The agency may be contacted at: 916-227-4364.



TRIS SRC#: 4946 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for TRIS was January, 1998.

Section 313 of the Emergency Planning and Community Right-to-Know Act (also known as SARA Title III) of 1986 requires the EPA to establish an inventory of Toxic Chemicals emissions from certain facilities (Toxic Release Inventory System). Facilities subject to this reporting are required to complete a Toxic Chemical Release Form(Form R) for specified chemicals.

#### D) DATABASES SEARCHED TO 1 MILE

ERNS SRC#: 6181 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for was August, 1999.

The Emergency Response Notification System (ERNS) is a national database containing records from October 1986 to the release date above and is used to collect information for reported releases of oil and hazardous substances. The database contains information from spill reports made to federal authorities including the EPA, the US Coast Guard, the National Response Center and the Department of Transportation. The ERNS hotline number is (202) 260-2342:

RCRA-LgGen SRC#: 6379 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for HWDMS/RCRIS was September, 1999.

The EPA's Resource Conservation and Recovery Act (RCRA) Program identifies and tracks hazardous waste from the point of generation to the point of disposal. The RCRA Facilities database is a compilation by the EPA of facilities which report generation, storage, transportation, treatment or disposal of hazardous waste. RCRA Large Generators are facilities which generate at least 1000 kg./month of non-acutely hazardous waste ( or 1 kg./month of acutely hazardous waste).

RCRA-SmGen SRC#: 6379 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for HWDMS/RCRIS was September, 1999.

The EPA's Resource Conservation and Recovery Act (RCRA) Program identifies and tracks hazardous waste from the point of generation to the point of disposal. The RCRA Facilities database is a compilation by the EPA of facilities which report generation, storage, transportation, treatment or disposal of hazardous waste. RCRA Small and Very Small generators are facilities which generate less than 1000 kg./month of non-acutely hazardous waste.

SPILL SRC#: 5849 VISTA conducts a database search to identify all sites within 1 mile of your property. The agency release date for Orange County-Industrial Cleanups was January, 1999.

This database is provided by the Orange County Health Care Agency. The agency may be contacted at: 714-834-3446.

### End of Report



APPENDIX (D

#### **APPENDIX D**

#### REFERENCES

- 1. City of San Juan Capistrano, 949-443-6345.
- 2. Continental Aerial Photo, Inc., 714-236-9084.
- 3. Fairchild Aerial Photo Collection, Whittier College, 562-307-4220.
- 4. California Regional Water Quality Control Board San Diego Region, Water Quality Control Plan for the San Diego Basin (9), dated September 8, 1994.
- 5. Vista Information Solutions 800-767-0403.
- 6. United States Geological Survey, <u>Topographic Maps for Cañada Gobernadora and San Juan Capistrano</u>, California Quadrangles, 1968, Photorevised 1988 and 1981, respectively.
- 7. Geologic Map Of Orange County California, Showing Mines and Mineral Deposits, compiled by P. K. Morton and R. V. Miller, and dated 1981.
- 8. Santa Margarita Water District, 949-459-6400.
- 9. County of Orange, Health Care Agency, 714-834-3446.